

LEE BROTHERS AUTOMOTIVE PTE LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

M/S ECICS LTD

7 TEMASEK BOULEVARD

#10-01 SUNTEC TOWER 1

SINGAPORE 038987

GBF9093S

ESTIMATE

VEHICLE NO : GBH5508D

MAKE/MODEL : TOYOTA DYNA

ACC DATE : 19/08/2024

not allowed
in
motor
20/8/24
d/s & 7500/-
Chaplin Henry
5 days

PARTICULAR

UNIT PRICE

AMOUNT

QTY	LIST PRICE	SS	SS
1	1 FRONT DOOR -RH <i>body 20</i>	1,896.50	1,896.50 ✓
2	1 FRONT DOOR SIDE MIRROR <i>320</i>	411.20	411.20 ✓
3	1 FRONT DOOR OUTER HANDLE <i>groth</i>	199.10	48.60 ✓
4	1 FRONT DOOR GLASS <i>sur</i>	855.71	855.71 X
5	1 FRONT DOOR GLASS OUTER MOULDING <i>cu7</i>	161.20	161.20 ✓
6	1 FRONT DOOR GLASS RUN CHANNEL <i>11</i>	281.63	281.63 X
7	1 FRONT DOOR GLASS GUIDE <i>11</i>	89.50	89.50 X
8	1 FRONT DOOR GLASS REGULATOR <i>surf</i>	381.95	381.95 ✓
9	1 FRONT DOOR GLASS REGULATOR MOTOR <i>sur</i>	431.50	431.50 X
10	1 FRONT DOOR SEAL <i>11</i>	116.23	116.23 X
11	1 FRONT DOOR W/STRIP <i>rec</i>	181.92	181.92 ✓
	1 FRONT DOOR BOARD <i>Torn</i>	531.20	531.20 ✓
12	1 FRONT DOOR INNER LOCK <i>Daye</i>	781.62	781.62 X
13	1 FRONT DOOR INSULATION <i>11</i>	130.20	130.20 ✓
14	1 FRONT DOOR CHECKER <i>11</i>	89.95	89.95 X
15	2 FRONT DOOR HINGES <i>lower surf</i>	115.00	230.00 12c
16	1 FRONT DOOR REAR PILLAR -RH <i>20/cu</i>	481.95	481.95 ✓
17	1 FRONT DOOR REAR PILLAR EMBLEM <i>rec</i>	86.65	86.65 ✓
18	1 FRONT WHEEL ARCH PANEL <i>body 20</i>	586.60	586.60 ✓
19	1 FRONT WHEEL ARCH PANEL SEAL <i>11</i>	199.10	199.10 ✓
20	1 FRONT WHEEL GUARD <i>cu7</i>	260.91	260.91 ✓
21	1 FRONT WHEEL HUB <i>Daye</i>	361.55	361.55 ✓
22	1 FRONT WHEEL BEARING <i>Daye</i>	211.50	211.50 ✓
23	1 FRONT SHOCK ABSORBER -RH <i>11</i>	280.90	280.90 X
24	1 FRONT UPPER ARM <i>11</i>	1,053.60	1,053.60 X
25	1 FRONT LOWER ARM <i>11</i>	760.60	760.60 X
26	1 FRONT LOWER ARM BALL JOINT <i>11</i>	211.60	211.60 X
27	1 FRONT KNUCKLE ARM <i>surf</i>	755.90	755.90 ✓
28	1 FRONT ANTI ROLL BAR <i>11</i>	485.60	485.60 X
29	1 FRONT STEP GARNISH <i>cu7</i>	312.60	312.60 ✓
30	1 REAR SIDE GATE -RH <i>20/surf</i>	1,899.66	1,899.66 ✓
31	1 REAR SIDE GATE STOPPER <i>11</i>	42.20	42.20 ✓
32	1 REAR SIDE STEP PANEL <i>11</i>	190.60	190.60 X
33	1 REAR PARTITION PANEL <i>11</i>	1,150.90	1,150.90 X
34	1 REAR SIDEGATE LOCK HINGE <i>11</i>	141.50	141.50 X
			16,092.83
		LESS 25%	4,023.21
			12,069.62

LEE BROTHERS AUTOMOTIVE PTE. LTD.

VEHICLE NO: GBH5508D

MODEL : TOYOTA DYNA

PARTICULAR		UNIT PRICE	AMOUNT
		S\$	S\$
<u>SPECIAL NETT ITEMS</u>			
1	1 FRONT WHEEL RIM -RH	180.00	180.00 X
1	1 FRONT TYRE	180.00	180.00 X
3	1 FRONT DOOR ROV STICKER	45.00	45.00 30
4	1 SIDE GATE TOP RAILING -RH	650.00	650.00 X
			<u>1,055.00</u>

<u>LABOUR CHARGES :</u>			
1	TO REMOVE & REPLACE FRONT UNDERCARRIAGE		300.00/SV
2	TO CONDUCT WHEEL ALIGNMENT		120.00 X
3	TO REMOVE & REFIX FRONT INTERIOR TRIMS TO ASSIST REPAIR		120.00 SV
4	TO TUFF KOTE		100.00 80
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		1,400.00 1000
6	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		1,500.00 800
			<u>3,000.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : **\$ 16,124.62**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1-9707-81
252
7280.85
30
2040
9390.85
202
7511.