

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/1C524080328/UV23**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: GBH 5508Dat Workshop m/s Lee book

of \_\_\_\_\_

Insured: GBF 9093S

Policy No. \_\_\_\_\_


Claims No. DMCV2400162H/ST

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: \$ 526.IDAC Accident Rpt: \_\_\_\_\_ Consistent? : **Yes or No**GIA / PR Seen: \_\_\_\_\_ Consistent? : **Yes or No**Est. Repairs: 5 days Res.: **Yes or No**Lum Sum: 20 % 3 Val.: **Yes or No**

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: CS08cVehicle: **IN / OUT**LTAS10273Veh No: GBH 5508D Yr Regn: 05/07/18Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or \_\_\_\_\_

Make: Triple Dyne c.c. 2982Colour: Silver A/C: **Insured / Std / NI / NA**Sp. Reading: 167792 T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: JTFAT354XOK21038Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **In order / Jammed / Leaked / Burnt or** okBrake: **In order / Jammed / Leaked / Burnt or**Modi: **Nil / S/Rim / STD A/Rim or**Tyre Size: **F:** 195-15-Keppon**R:** 155-12**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO or**Front: 6 Rear: 6R/Bal. \_\_\_\_\_ mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/08/24 D.O.I. 20/8/24

Survey held at \_\_\_\_\_

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop or**0/5 Frt, 0/5 BodyThe **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time

Action / Instruction

29/8/2429/8/24 1/5 @ 7500 insured MR Lee (red 8624.62, 53%)

Date/Time, File Pass to?

☐: **Preli. Report**

1)

☐: **Final Report**

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	508C
<b>Vehicle Details</b>	
Vehicle No.:	GBH5508D
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2797882
Chassis No.:	JTFAT35YX0K210385
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	05 Jul 2018
First Registration Date:	05 Jul 2018
Transfer Count:	1
Actual ARF Paid:	\$1,355.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	04 Jul 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$26,533.00
COE Rebate Amount:	\$10,273.00
<b>Total Rebate Amount:</b>	<b>\$10,273.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 20 Aug 2024

OK



STAND TO WIN \$45,000  
IN OUR PML45 CELEBRATORY DRAW.\*

\*T&amp;Cs apply.

[Find out more](#)PML  
45

Performance Motors

## Post an Advertisement

Sell it yourself! Advertise it at just

**\$72 until it's SOLD!**[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

Toyota Prius Plus Hybrid 1.8A. 1 Owner. 7 Seater.

1 Owner. 1 Year Warranty & 1  
Servicing. Borneo Maintained.  
7 Seater. Non-phv.  
Borneo Motors (S) StarAd**PRIME MOTOR & LEASING**

(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.Sort by   results/page

11 vehicles



TOYOTA DYNA

Any Category

Advanced Search

Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	TOYOTA DYNA		Any	Any	2018	Any	Any	Any	Available

**Toyota Dyna 150 3.0A**

Fuel Type: Diesel

\$59,988

\$16,400 /yr

17-Apr-2018

2,982 cc

109,000 km

Truck

Available

Toyota Dyna 150 auto selling at manual price! Top up \$168 only and we will cover your servicing until change of owner or scrap! 24hr towing service! New paint work done! FREE optional canopy! Checkered plate done! Very well maintained unit with only 109000km do...

ABS Bus Pte Ltd

Posted: 20-Aug-2024

PREMIUM AD

**Toyota Dyna 150 3.0M**

Fuel Type: Diesel

\$60,988

\$14,380 /yr

16-Nov-2018

2,982 cc

-

Truck

Available

Need no introduction! The best 10 feet lorry in the market! Well maintained unit! Canopy & Checkered Plate Can Be Arranged! Original seat cushion! Just only a fresh coat of paint done up only! Top \$168 for lifetime servicing and 2 years warranty! We take in high trade in...

ABS Bus Pte Ltd

Posted: 20-Aug-2024

PREMIUM AD

**Toyota Dyna 150 3.0M**

Fuel Type: Diesel

\$51,988

\$14,120 /yr

26-Apr-2018

2,982 cc

-

Truck

Available

With plate number 5566. Good condition unit. View to believe. National day promotion, top up one time payment \$59 for whole life servicing package, trade in welcome. Call us now to arrange for viewing.

ABS Bus Pte Ltd

Posted: 19-Aug-2024

PREMIUM AD

**Toyota Dyna 150 3.0M**

Fuel Type: Diesel

\$58,800

\$13,680 /yr

07-Dec-2018

2,982 cc

-

Truck

Available

Cheapest best deal in market, retractable canopy, free warranty with official certificate, high loan available, free servicing, accident free, STA or Vicom evaluation inspection are welcome, bank and in house loan available at competitive interest rate, warranty not by third par...

CARWAY

Posted: 19-Aug-2024

PREMIUM AD

**Toyota Remote Key Duplicate/Repair Service**

The price is dependent on car spec and key spec, for repair or replace the battery price from \$10 onwards.

[More info about this product](#)**Toyota Dyna 150 3.0M**

Fuel Type: Diesel

\$59,800

\$13,790 /yr

21-Dec-2018

2,982 cc

-

Truck

Available

PREMIUM AD

# LEE BROTHERS AUTOMOTIVE PTE LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

M/S ECICS LTD

7 TEMASEK BOULEVARD

#10-01 SUNTEC TOWER 1

SINGAPORE 038987

GBF9093S

## ESTIMATE

VEHICLE NO : GBH5508D

MAKE/MODEL : TOYOTA DYNA

ACC DATE : 19/08/2024

Not Allowed  
den  
moru-  
20/8/24  
4/5 & 7500/-  
Chaple Henry  
5 days

### PARTICULAR

### UNIT PRICE

### AMOUNT

#### QTY

#### SS

#### SS

#### LIST PRICE

1	1	FRONT DOOR -RH	body	1,896.50	1,896.50	/
2	1	FRONT DOOR SIDE MIRROR	320	411.20	411.20	/
3	1	FRONT DOOR OUTER HANDLE	groth	199.10	48.60	/
4	1	FRONT DOOR GLASS	sur	855.71	855.71	X
5	1	FRONT DOOR GLASS OUTER MOULDING	cu7	161.20	161.20	/
6	1	FRONT DOOR GLASS RUN CHANNEL	17	281.63	281.63	X
7	1	FRONT DOOR GLASS GUIDE	17	89.50	89.50	X
8	1	FRONT DOOR GLASS REGULATOR	surf	381.95	381.95	/
9	1	FRONT DOOR GLASS REGULATOR MOTOR	sur	431.50	431.50	x
10	1	FRONT DOOR SEAL	17	116.23	116.23	x
11	1	FRONT DOOR W/STRIP	rec	181.92	181.92	/
	1	FRONT DOOR BOARD	born	531.20	531.20	/
12	1	FRONT DOOR INNER LOCK	Daye	781.62	781.62	/
13	1	FRONT DOOR INSULATION	17	130.20	130.20	X
14	1	FRONT DOOR CHECKER	17	89.95	89.95	X
15	2	FRONT DOOR HINGES	lower surf	115.00	230.00	IPC
16	1	FRONT DOOR REAR PILLAR -RH	22/cu	481.95	481.95	/
17	1	FRONT DOOR REAR PILLAR EMBLEM	rec	86.65	86.65	/
18	1	FRONT WHEEL ARCH PANEL	body	586.60	586.60	/
19	1	FRONT WHEEL ARCH PANEL SEAL	17	199.10	199.10	/
20	1	FRONT WHEEL GUARD	cu7	260.91	260.91	/
21	1	FRONT WHEEL HUB	Daye	361.55	361.55	/
22	1	FRONT WHEEL BEARING	Daye	211.50	211.50	/
23	1	FRONT SHOCK ABSORBER -RH	17	280.90	280.90	x
24	1	FRONT UPPER ARM	17	1,053.60	1,053.60	X
25	1	FRONT LOWER ARM	17	760.60	760.60	X
26	1	FRONT LOWER ARM BALL JOINT	17	211.60	211.60	X
27	1	FRONT KNUCKLE ARM	surf	755.90	755.90	/
28	1	FRONT ANTI ROLL BAR	17	485.60	485.60	X
29	1	FRONT STEP GARNISH	cu7	312.60	312.60	/
30	1	REAR SIDE GATE -RH	22/surf	1,899.66	1,899.66	/
31	1	REAR SIDE GATE STOPPER	17	42.20	42.20	/
32	1	REAR SIDE STEP PANEL	17	190.60	190.60	X
33	1	REAR PARTITION PANEL	17	1,150.90	1,150.90	X
34	1	REAR SIDEGATE LOCK HINGE	17	141.50	141.50	X

LESS 25%

16,092.83

4,023.21

12,069.62



# LEE BROTHERS AUTOMOTIVE PTE. LTD.

VEHICLE NO: GBH5508D

MODEL : TOYOTA DYNA

PARTICULAR		UNIT PRICE	AMOUNT
		S\$	S\$
<b><u>SPECIAL NETT ITEMS</u></b>			
1	1 FRONT WHEEL RIM -RH	180.00	180.00 X
1	1 FRONT TYRE	180.00	180.00 X
3	1 FRONT DOOR ROV STICKER	45.00	45.00 30
4	1 SIDE GATE TOP RAILING -RH	650.00	650.00 X
			<u>1,055.00</u>
<b><u>LABOUR CHARGES :</u></b>			
1	TO REMOVE & REPLACE FRONT UNDERCARRIAGE		300.00/50
2	TO CONDUCT WHEEL ALIGNMENT		120.00 X
3	TO REMOVE & REFIX FRONT INTERIOR TRIMS TO ASSIST REPAIR		120.00 50
4	TO TUFF KOTE		100.00 80
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		1,400.00 1000
6	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		1,500.00 800
			<u>3,000.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : **\$ 16,124.62**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

1- 9707-81  
252  
7280.85  
30  
2010  
9390.85  
202  
7512.

View Received Message

This mail is associated with :

\*GBH5508D (DMCV2400162H/ST)

[GBF9093S]

TP

-

Aug 19 2024 12:00AM

LEE BROTHERS AUTOMOTIVE PTE. LTD.

- Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

From

ECICS Limited (HQ) (ECICS), sent on 28/08/2024 18:16 PM.

To

LKK\_HQ

Subject

Alert - Adj Mandate Approved (S\$0.00) - GBH5508D - Claim Handler: Sharon Tan Chow Yen

Approved:0.00:We are of the view that BOLA 28G is applicable. According to the scenario, we are not liable for the accident. Please assist to submit your survey on a WP basis.

DOCUMENTS SUMMARY

There are no documents.