

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHD4349C

Make : HYUNDAI

Model : IONIQ(G3)

Date: 20/08/2024

Insurance: ECICS

MVA: MS. LOKE YY

| Qty                                    | Parts Description / Labour                     | Type | Unit Price | Amount       |
|--|--|------|------------|--------------|
| 1                                      | REAR BUMPER COVER / BR                         |      |            | \$459.40 /   |
| 10                                     | REAR BUMPER CLIPS / MC                         |      |            | \$22.00 /    |
| 1                                      | REAR BUMPER CENTRE MOULDING ASSY / BR          |      |            | \$451.25 /   |
| 1                                      | REAR BUMPER REINFORCEMENT ? x nn               |      |            | \$394.80     |
| 1                                      | REAR BUMPER REINFORCEMENT BRACKET LH RH ? x nn |      |            | \$138.10     |
| 2                                      | REAR BUMPER SIDE BRACKET LH RH ? x nn          |      | \$55.80    | \$111.60     |
| 1                                      | ANTENNA SMARTKEY ? x nn                        |      |            | \$40.50      |
| 1                                      | REAR BUMPER FOG LAMP ? x nn                    |      |            | \$201.50     |
| 1                                      | REAR BUMPER TOWING COVER / MIS                 |      |            | \$98.80 /    |
| 1                                      | BOOT LID GLASS LOWER x nn                      |      |            | \$584.90     |
| 1                                      | REAR PANEL GARNISH x nn                        |      |            | \$346.80     |
| 1                                      | REAR PANEL x R                                 |      |            | \$532.00     |
| 1                                      | REAR BUMPER LOWER CENTRE MOULDING / BR         |      |            | \$155.00 /   |
| 1                                      | REAR BUMPER REFLECTOR LH x nn                  |      |            | \$55.00      |
| SUB TOTAL                              |  |      | 1186.45    | \$3,591.65   |
| LESS 20%                               |  |      | -20%       | \$718.33     |
| DISCOUNTED TOTAL                       |  |      | 949.16     | \$2,873.32   |
| REAR NUMBER PLATE WITH TRIM COVER / BR |  |      |            | \$50.00      |
| RENEW ADVERTISEMENT STICKER / MC       |  |      |            | \$200.00     |
| REAR BUMPER REVERSE SENSOR / BR        |  |      |            | \$180.00     |
| NETT                                   |  |      | 430        | \$430.00     |
| Labour Charge                          |  |      |            |              |
| PANEL BEATING                          |  |      |            | \$800.00 380 |
| SPRAY PAINTING CHARGE                  |  |      |            | \$300.00 280 |
| CHK ALL LIGHTING/ WIRING               |  |      |            | \$60.00 30   |
| TUFF KOTE                              |  |      |            | \$60.00 X    |
| REMOVE/REFIX REVERSE SENSOR            |  |      |            | \$80.00 20   |
| TOTAL LABOUR                           |  |      | 710        | \$1,300.00   |
| ESTIMATE TOTAL                         |  |      |            | \$4,603.32   |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Steve (LKK)

20/8/24, 4.00pm

m ll

L/S

M KL 17

2 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: .

Date:

2089.16

L/S - 1671.32  
= 1650