

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	SOMPO INSURANCE SINGAPORE PL		Ref:	CS/SMO24080330/Aqp3m4	
	50 RAFFLES PLACE #03-03		Date:	26/09/2024	
	SINGAPORE LAND	OWER SINGAPORE 048623	Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 2398J	Veh. Inspected	SNF 6017R	
	Policy No.	D24MTHCVE000624	Coverage	0	
	Claim No.	CMTD2402692/AGC	Excess	\$0.00	
	Assign From	GRACE TEO	Assign Date	20/08/2024	
2.	2. Vehicle Details				
	Make & Model	HONDA STEPWAGON 2.0 A	c.c	1998	
	Engine No.	K20A2498232	Year of Reg.	23/05/2006	
	Chassis No.	RG11040870	Colour	BROWN	
	Odometer	191334 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/60R16	ARIVO	6	
	L/H Front Tyre	205/60R16	ARIVO	6	
	R/H Rear Tyre	205/60R16	ARIVO	6	
	L/H Rear Tyre	205/60R16	ARIVO	6	
4.					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date				
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP - 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.					
ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					