

(08/11/13) Wef

ASS. REC. BY:

REF:

CS/A1624080331/Rvp3

746C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNL 6399G

at Workshop m/s PREMIUM

of BLOW SECTOR

Insured: ALH

Policy No. 7230071311

Claims No. 0601440195SG

Sum Insured: Excess: 300 TBA

(Client's Record)

Make of Veh:

(Policy Condition)

3pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 178K

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIA IT - 81K

13/9/24 Rasul confirmed final fig \$16,800.96 (Red 18,919.04, 52%)

Veh No:

SNL 6399G

Yr Regn:

2023 JULY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

AUDI A3 SP 1.0 TFSI STRONIC c.c 999

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading:

26757

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VWU 222649NA099008

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A. 20/08/24

D.O.I. 21/08/24

Survey held at

BLOW

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair: 7

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0625/2024/KS
DATE : 20-Aug-24
WIP : 27711

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : AZNI BIN MARMIM
ADDRESS : BLK 315A PUNGGOL WAY
#03-641
SINGAPORE 821315
TELEPHONE : HP +65 96851674
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230071311-01
VEHICLE NO : **SNL 6399 G**
MODEL CODE : A3 SPORTBACK 1.0 TFSI
MODEL YEAR : 24/7/2023
ENGINE NO : DLA E12385
CHASSIS NO : WAUZZZGY9NA099008
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Aug-24
PLACE OF ACCIDENT : TAMPINES RD, TOWARDS KPE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNL 6399 G.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00 /	
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	280.00 /	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,450.00 / 1000	
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.	\$	2,450.00 / 1650	
6	TO REMOVE AND REINSTALL FRONT WHEEL SUSPENSION ASSY.	S/N \$	3,200.00 ?	
7	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00 ?	
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00 /	
TOTAL LABOUR CHARGES		: \$	10,022.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNL 6399 G.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de-</i>	1	\$	1,889.00
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$	311.00
3	FRONT BUMPER BRACKET <i>?</i>	1	\$	36.00
4	FRONT BUMPER CLOSIGN ELEMENT - RH <i>?</i>	1	\$	145.00
5	FRONT BUMPER CLOSING ELEMENT - LWOER CENTRE <i>?</i>	1	\$	298.00
6	FRONT BUMPER AIR GUIDE - RH <i>X</i>	1	\$	75.00
7	FRONT BUMPER SPOILER <i>?</i>	1	\$	366.00
8	FRONT BUMPER COVER TRIM - RH <i>X</i>	1	\$	117.00
9	FRONT BUMPER AIR GUIDE GRILLE - RH <i>?</i>	1	\$	192.00
10	FRONT AIR GUIDE GRILLE DUMMY COVER - RH <i>X</i>	1	\$	41.00
11	FRONT AIR GUIDE GRILLE PARKING AID SENSOR - RH <i>?</i>	1	\$	300.00
12	FRONT PARKING AID SENSOR SEAL RING <i>X</i>	4	\$	57.00
13	FRONT BUMPER GUDIE SECTION - RH <i>?</i>	1	\$	61.00
14	LED HEADLIGHT - RH <i>cut / photo?</i>	1	\$	4,583.00
15	LIFT CYLINDER - RH <i>?</i>	1	\$	230.00
16	LIFT CYLINDER HOSE - RH <i>X</i>	1	\$	118.00
17	FRONT FENDER - RH <i>bl-</i>	1	\$	1,318.00
18	FRONT FENDER CLOSING ELEMENT - RH <i>?</i>	1	\$	36.00
19	FRONT FENDER RIVET - RH <i>new</i>	3	\$	13.00
20	FRONT FENDER BRACKET - RH <i>?</i>	1	\$	56.00
SUB TOTAL SPARE PARTS		:	\$	10,242.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNL 6399 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - RH ?	1	\$	56.00
22	FRONT FENDER BRACKET - RH ?	1	\$	45.00
23	FRONT FENDER BRACKET - RH ?	1	\$	122.00
24	FRONT FENDER ATTACHMENT PARTS - RH X	1	\$	135.00
25	FRONT WHEEL HOUSING LINER SEAL - RH de ?	1	\$	43.00
26	FRONT WHEEL HOUSING LINER - RH de	1	\$	204.00
27	WHEEL HOUSING LINER ATTACHMENT PARTS - RH ?	1	\$	139.00
28	FRONT ALUMINIUM RIM - RH sea	1	\$	1,614.00
29	FRONT ALUMINIUM RIM RUBBER VALVE - RH re	1	\$	5.00
30	FRONT LOWER ARM - RH ?	1	\$	422.00
31	FRONT STABILIZER, COMPLETE ?	1	\$	479.00
32	FRONT WHEEL BEARING HOUSING - RH ?	1	\$	669.00
33	FRONT WHEEL HUB ?	1		TBC
34	FRONT GUIDE JOINT - RH ?	1	\$	145.00
35	FRONT COUPLING ROD - RH ?	1	\$	112.00
36	FRONT LOWER ARM COVER - RH ?	1	\$	11.00
37	DRIVESHAFT - RH ?	1	\$	2,393.00
38	STEERING GEAR ?	1	\$	6,300.00
39	HEAT SHIELD PLATE ?	1	\$	158.00
40	SUBFRAME ?	1	\$	939.00
41	SUBFRAME BUSHES ?	1	\$	189.00
42	FRONT TYRE - RH X	1		TBC
43	SUNDRIES ?	1	\$	1,000.00
TOTAL SPARE PARTS		:	\$	25,422.00
TOTAL LABOUR CHARGES		:	\$	10,022.00
GRAND TOTAL		:	\$	35,444.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Repair - Hp 90010668
: 21/08/24
: Sclayp
: Repair
: Repair by paint / Excess: TRA

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	746C
Vehicle Details	
Vehicle No.:	SNL6399G
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2024
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC
Primary Colour:	Grey
Manufacturing Year:	2022
Engine No.:	DLAE12385
Chassis No.:	WAUZZZGY9NA099008
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$27,197.00
Original Registration Date:	24 Jul 2023
First Registration Date:	24 Jul 2023
Transfer Count:	0
Actual ARF Paid:	\$15,076.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2033
PARF Rebate Amount:	\$11,307.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jul 2033
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$95,202.00
COE Rebate Amount:	\$84,914.00
Total Rebate Amount:	\$96,221.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 22 Aug 2024

OK

Audi A3 Sportback Mild Hybrid 1.0A TFSI

\$166,999 Instalment \$1,400/mth

PREMIUM AD

Apply for 2.48% loan

Shortlist

Loan Calculator



Overview Financial Photo Research

Depreciation	 \$18,370 / year
Reg. Date	29-Nov-2022 (8yrs 3mths 6days COE left)
Manufactured	 2022
Mileage	3,000 km (1.7k / year)
Transmission	Auto
Engine Cap	999 cc
Road Tax	 \$392 / year
Power	81.0 kW (108 bhp) View specs of the Audi A3 Sportback Mild Hybrid (2021-2024)
Curb Weight	 1,355 kg
Fuel Type	Petrol-Electric
COE	 \$90,589
OMV	 \$27,160
APF	 \$22,000