

Name & Address:
FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
motor_claims@first-insurance.com.sg

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

Policy No:

Vehicle No:

SNF9629E

Brand & Model:

MG ZS EV UK

Chassis/VIN No:

LSJW74093MZ168968

Date Of Registration:

6/30/2022

Date:

19-Aug-24

Franchise:

MG

Contact Person (Eurokars):

WONG

Contact No (Eurokars):

6331 0680

REPAIR ESTIMATE

P/P 83396

NH Approval
Morans
take photo of the car
3 days
28/8/24

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER UPPER	10344162-SPRP	1		-	\$ 974.00
2	NUT-RR BPR FASCIA	90003375	6		-	\$ 6.00
3	NUT-RR BPR FASCIA	50012569	2		-	\$ 4.00
4	BRACKET-RR PARK DIST CONT SEN LH	10345448	1		-	\$ 27.00
5	BRACKET-RR PARK DIST CONT SEN CENTER	10343137	1		-	\$ 27.00
6	BRACKET-RR PARK DIST CONT SEN RH	10345485	1		-	\$ 27.00
7	REAR BUMPER LOWER	10344164	1		-	\$ 593.00
8	COVER-RR TOW HOOK OPG	10344260	1		-	\$ 14.00
9	SPOILER-RR BPR LWR	10344180	1		-	\$ 394.00
10	RIVET-RR BPR FASCIA	30081918	2		-	\$ 8.00
11	NUT-RR BPR FASCIA	90003375	6		-	\$ 6.00

Sub-Total (Parts Price) \$ - \$ 2,080.00

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE & REPLACE REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA. 792	792	\$ 1,584.00
2	TO RESPRAY REAR BUMPER. 756	756	\$ 1,512.00
3	TO TRANSFER REVERSE SENSORS.	11X	\$ 330.00
4	TO APPLY THREEBOND ULTRA BODY COATING	NETT	\$ 150.00
5	TO ISOLATE THE EV BATTERY DURING THE REPAIRS INCLUDING CHARGING OF THE BATTERY.	NETT X	\$ 250.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 300.00
8	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU). 11X	11X	\$ 250.00
9	SUNDRIES	NETT 20	\$ 50.00

Sub-Total (Labour Price) \$ - \$ 4,676.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Rear licence plate seen 70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	REVISED	PRICE
Parts Price	\$ -	\$ 2,080.00
Labour Price	\$ -	\$ 4,676.00
Total (Initial Estimate)	\$ -	\$ 6,756.00
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 6,756.00

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

REPAIR ESTIMATE

Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	6,756.00
GST	9%	\$	-	\$ 608.04
GRAND TOTAL	\$	-	\$	7,364.04

Name & Address:

FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
motor_claims@first-insurance.com.sg

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

Vehicle No:

SNF9629E

Brand & Model:

MG ZS EV UK

Chassis/VIN No:

LSJW74093MZ168968

Mileage:

44742

Date:

19-Sep-24

Franchise:

MG

Contact Person (Eurokars):

WONG

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FOG LAMP CHROME LH	10014696	1		one	\$ 97.00
2	CLIP-RR WHL MLDG	10659985	10		ten	\$ 200.00

Sub-Total (Parts Price) \$ - \$ 297.00

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO SUPPLY REAR NUMBER PLATE	scr	\$ 70.00

Survey Date & Time:

Repair Days:

Sub-Total (Labour Price) \$ - \$ 70.00

Surveyor Remarks:

Parts Price \$ - \$ 297.00

Labour Price \$ - \$ 70.00

Total (Supp 1) \$ - \$ 367.00