

Name & Address:

FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
motor_claims@first-insurance.com.sg

Email/Fax No:

Contact No:

Vehicle No:

SNF9629E

Date:

22-Oct-24

Brand & Model:

MG ZS EV UK

Franchise:

MG

Chassis/VIN No:

LSJW74093MZ168968

Contact Person (Eurokars):

WONG

Type of Claim:

THIRD PARTY

Policy No:

Date Of Registration:

30/06/2022

Contact No (Eurokars):

6331 0680
PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER UPPER	10344162-SPRP	1		-	\$ 974.00
2	NUT-RR BPR FASCIA	90003375	6	A	\$ 6.00	\$ 6.00
3	NUT-RR BPR FASCIA	50012569	2	A	\$ 4.00	\$ 4.00
4	BRACKET-RR PARK DIST CONT SEN LH	10345448	1		-	\$ 27.00
5	BRACKET-RR PARK DIST CONT SEN CENTER	10343137	1		-	\$ 27.00
6	BRACKET-RR PARK DIST CONT SEN RH	10345485	1		-	\$ 27.00
7	REAR BUMPER LOWER	10344164	1	A	\$ 593.00	\$ 593.00
8	COVER-RR TOW HOOK OPG	10344260	1		-	\$ 14.00
9	SPOILER-RR BPR LWR	10344180	1	A	\$ 394.00	\$ 394.00
10	RIVET-RR BPR FASCIA	30081918	2	A	\$ 8.00	\$ 8.00
11	FOG LAMP CHROME LH	10014696	1	A	\$ 97.00	\$ 97.00
12	CLIP-RR WHL MLDG	10659985	10	A	\$ 200.00	\$ 200.00
13	NUT-RR BPR FASCIA	90003375	6	A	\$ 6.00	\$ 6.00

Sub-Total (Parts Price) \$ 1,308.00 \$ 2,377.00

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE & REPLACE REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA.	\$ 792.00	\$ 1,584.00
2	TO RESPRAY REAR BUMPER.	\$ 756.00	\$ 1,512.00
3	TO TRANSFER REVERSE SENSORS.	-	\$ 330.00
4	TO APPLY THREEBOND ULTRA BODY COATING	\$ 150.00	\$ 150.00
5	TO ISOLATE THE EV BATTERY DURING THE REPAIRS INCLUDING CHARGING OF THE BATTERY.	-	\$ 250.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 300.00
8	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU).	-	\$ 250.00
9	TO SUPPLY REAR NUMBER PLATE WITH CASING	\$ 70.00	\$ 70.00
10	SUNDRIES	\$ 20.00	\$ 50.00

Survey Date & Time:

Repair Days:3

Excess:

Sub-Total (Labour Price) \$ 2,088.00 \$ 4,746.00

Surveyor Remarks:

	REVISED	PRICE
Parts Price	\$ 1,308.00	\$ 2,377.00
Labour Price	\$ 2,088.00	\$ 4,746.00
Total (Initial Estimate)	\$ 3,396.00	\$ 7,123.00

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	3,396.00	\$	7,123.00
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	3,396.00	\$	7,123.00
GST 9%	\$	305.64	\$	641.07
GRAND TOTAL	\$	3,701.64	\$	7,764.07