

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SMADMIN@SM-AUTOMOTIVE.SG

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

19/06/2024

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 13/06/2024

TP Chim.

Hui Rong

Estimated repair cost for vehicle no: GBB5553D TOYOTA DYNA 150 MANUAL 3SEATER

CHASSIS: JTFAT35Y70K200705 (2009)

S/N	Qty	Items	U/price	Amount
21	1	FRONT BUMPER	\$698.10	\$698.10 +
22	1	RH FRONT BUMPER BRACKET	\$121.10	\$242.20 +
26	1	RH FRONT HEADLAMP	\$556.20	\$556.20 ✓
27	1	RH FRONT CORNER PANEL	\$245.60	\$245.60 ✓
31	1	RH FRONT PANEL PROTECTOR	\$148.10	\$148.10 ✓
41	1	RH FRONT DOOR	\$1,218.90	\$1,218.90 ✓
42	2	RH FRONT DOOR HINGE	\$78.90	\$157.80 +
43	1	RH FRONT DOOR CHECKER	\$121.90	\$121.90 +
44	1	RH FRONT DOOR WEATHER STRIPE	\$178.40	\$178.40 +
45	1	RH FRONT DOOR INNER TRIM BOARD	\$642.60	\$642.60 +
46	1	RH FRONT DOOR POWER WINDOW REGULATOR GEAR	\$541.60	\$541.60 +
47	1	RH FRONT DOOR POWER WINDOW MOTOR	\$412.80	\$412.80 +
50	1	RH FRONT DOOR GLASS INNER CHANNEL	\$143.50	\$143.50 +
51	1	RH FRONT STEP GARNISH	\$318.90	\$318.90 +
52	1	RH FRONT STEP PANEL	\$442.30	\$442.30 +
53	1	RH FRONT DOOR PILLER OUTER	\$1,944.30	\$1,944.30 +
54	1	RH FRONT DOOR PILLAR INNER	\$1,794.30	\$1,794.30 +

216880

162666

TOTAL :

\$9,807.50

LESS 25 %

\$2,451.88

SUB-TOTAL :

\$7,355.63

GBB5553D TOYOTA DYNA

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	RH FRONT DOOR INNER TRIM BOARD CLIPS <i>new</i>	\$80.00	\$80.00 <i>x</i>
2	1	RH FRONT COMPANY STICKER <i>new</i>	\$800.00	\$800.00 <i>150</i>
3	1	RH FRONT DOOR LTA STICKER <i>new</i>	\$50.00	\$50.00 <i>30</i>

180

TOTAL: \$930.00

TOTAL PARTS : \$8,285.63

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & TRANSFER ALL RH FRONT DOOR FITTING

new
\$1,000.00
\$1,000.00 *new*
\$100.00 *30*
\$300.00 *30*
\$300.00 *80*

940

Subtotal :- \$2,700.00

Total:- \$10,985.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
1/S 19/06/24.

03849

Total: 2746.66

L/S 2.2K

2.2K