

CARSMITH PRIVATE LIMITED
PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE415875
 Tel: 9091 0000/ Email: info@carsmith.biz

*Not Authorized
 as
 moras
 9/9/24
 2/s #3600
 telephone. At 14
 4 days.*

VEHICLE NO: PC4415E
 MAKE & MODEL: TOYOTA HIACE
 DOA: 19.08.2024
 CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
RAILING BARING	2	\$ 320.00	nn X
REAR FENDER RH	1	\$ 2,745.00	body 20/cne
REAR FENDER INNER RH	1	\$ 3,210.00	R X
RERA BUMPER	1	\$ 625.00	born
TAILGATE	1	\$ 1,365.00	11 X
TAIL GATE LOCK	1	\$ 280.00	11 X
REAR TAIL LAMP RH	1	\$ 640.00	cne
REAR TAIL LAMP PANEL RH	1	\$ 270.00	cut

\$ 9,455.00
 LESS 25% \$ 945.50
SUB TOTAL \$ 8,509.50

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR RIM RH	1	\$ 500.00	11 X
SIDE DOOR CLIP	1	\$ 50.00	11 X
TAILGATE CLIP	1	\$ 52.00	11 X
JOINT SEALANT	1	\$ 120.00	50 S/N

SUB TOTAL \$ 722.00

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 300.00	20
REMOVE AND ^{refit} RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND REFIT AND RENEW REAR EXHAUST	1	\$ 150.00	11 X
REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 300.00	100
PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,200.00	800
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 1,200.00	500
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 100.00	40

SUB TOTAL \$ 3,370.00

GRAND TOTAL \$ 12,601.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*P- 397840
 252
 298388
 50
 1490
 42388
 202
 3619*