

ASS. REC. BY:

REF:

A161

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11-30am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 150k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.8% %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STF 3710

Yr Regn:

09, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tesla Model 3

C.C.

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

44476

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LRW 3F7EL 8MC 263490

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

17/8/24

D.O.I.

20/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frg

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/9 @ 2428.28 Calm

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Date: 19-8-2024
Vehicle No: SJF371D
Model: Tesla Model 3
Chassis: LRW3F7EL6MC263490
Reg.Year: 15.9.2021

Not withair
Runny B&Pain
4 days
@ 2428.28

Third Party Insurer: AIG
Third Party Veh No: SGB4042J
Date of Accident: 17/8/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	<i>Buy/Re</i>	\$766.00 ✓
2	FRONT LH BUMPER RETAINER	1		<i>DIY</i> \$1.86 ✓
3	FRONT LH BUMPER SIDE SUPPORT BRACKET	1		<i>CM</i> \$12.14 ✓
4	FRONT BUMPER ENERGY ABSORBER	1		<i>PU</i> \$46.72 X
5	FRONT LH FOG LAMP	1		<i>PU</i> \$271.02 X
6	FRONT PARKING SENSOR	<i>2</i>	\$163.55	<i>DIY</i> \$327.10 ✓
7	FRONT PARKING SENSOR MOUNTING BRACKET	6	\$4.67	<i>PU</i> \$28.02 ✓
8	FRONT LH HEADLAMP	1		<i>PU</i> \$1,741.00 X
9	FRONT LH FENDER PANEL	1		<i>PU</i> \$448.59 ✓
10	FRONT LH FENDER LINER	1		<i>CM</i> \$116.82 ✓
11	FRONT LH KNUCKLE ARM	1		<i>PU</i> \$420.56 X
12	FRONT LH KNUCKLE HUB + BEARING	1		<i>PU</i> \$149.53 X
13	FRONT LH LOWER ARM - STRAIGHT	1		<i>PU</i> \$242.99 X
14	FRONT LH LOWER ARM - CURVED	1		<i>PU</i> \$224.29 X
15	FRONT LH UPPER ARM	1		<i>PU</i> \$121.49 X
16	FRONT LH WHEEL RIM	1		<i>PU</i> REPAIR X
SUB TOTAL				\$4,918.13
LESS 10%				-\$491.81
PARTS TOTAL				\$4,426.32

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>PU</i> \$50.00 ✓
2	FRONT FENDER LINER CLIPS	1		<i>PU</i> \$50.00 ✓
3	FRONT BUMPER LOWER COVER CLIPS	1		<i>PU</i> \$50.00 X
S/N TOTAL				\$150.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT LH ACCIDENT AREAS & ETC. \$700.00 *400*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT LH FENDER, ETC \$700.00 *440*

TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR ~ \$300.00 X

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19-8-2024
Vehicle No: SJF371D
Model: Tesla Model 3
Chassis: LRW3F7EL6MC263490
Reg.Year: 15.9.2021

Third Party Insurer: AIG
Third Party Veh No: SGB4042J
Date of Accident: 17/8/2024
Estimator: Loong
Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.

301 \$100.00

TO REMOVE AND REFIT FRONT PARKING SENSORS

601 \$100.00

TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT

nn \$120.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$100.00 15/

TO READJUST AND REALIGN HEADLAMP AIM

nn \$100.00 X

LABOUR TOTAL \$2,220.00

TOTAL \$6,796.32

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9019 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



➤ [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 636J

Vehicle Details

Vehicle No.: SJF371D

Vehicle to be Exported: No

Intended Deregistration Date: 19 Aug 2024

Vehicle Make: TESLA

Vehicle Model: MODEL 3 PERFORMANCE

Primary Colour: Red

Manufacturing Year: 2021

Engine No.: -

Chassis No.: LRW3F7EL6MC263490

Maximum Power Output: 377.0 kW (505 bhp)

Open Market Value: \$73,264.00

Original Registration Date: 15 Sep 2021

First Registration Date: 15 Sep 2021

Transfer Count: 0

Actual ARF Paid: \$58,876.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Sep 2031

PARF Rebate Amount: \$44,157.00

Intended COE Rebate Details

COE Expiry Date: 14 Sep 2031

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$62,600.00

COE Rebate Amount: \$44,265.00

Total Rebate Amount: \$88,422.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 19 Aug 2024

OK