

**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 16)

### PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A





**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**



**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**





**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**



**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**






**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**



**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**





**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**



**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**






**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**





**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**





**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**



**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**





**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**



**PHOTOGRAPHS FOR VEHICLE NO. : SMD 3695A**

