

FASTECH AUTO PTE LTD  
1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883  
Tel No: 67452063/ 67467158 Fax No: 67458520  
Tax Reg No : 200006262D

not Audited  
mean  
18/6/24  
\$7945.60  
4 hrs.

VEHICLE No: SGV 68G

|      |                                              |              |                      |
|------|----------------------------------------------|--------------|----------------------|
| 1PC  | FRONT BUMPER                                 | cut to 1874  | \$2,850.00 ✓         |
| 1PC  | FRONT BUMPER CENTRE LOWER CHROME MOULDING    | see          | \$355.00 X           |
| 1PC  | FRONT BUMPER PDC SENSOR O/S                  | modification | 201.00 \$365.00 ✓    |
| 1PC  | FRONT BUMPER BEAM                            | 11           | \$815.00 X           |
| 1PC  | FRONT BUMPER SIDE RETAINER O/S               | see          | \$108.00 X           |
| 1SET | FRONT BUMPER CLIPS & RIVET                   | Rel          | \$60.00 ✓            |
| 1PC  | HEADLAMP ASSY O/S                            | scr/line     | 2771.22 \$9,800.00 ✓ |
| 1PC  | FRONT FENDER O/S                             | R            | \$1,599.00 X         |
| 1PC  | FRONT FENDER INNER SHIELD O/S                | 11           | \$365.00 X           |
| 1SET | FRONT FENDER INNER SHIELD CLIPS O/S          | 11           | \$60.00 X            |
| 1PC  | FRONT SPORT RIM '19 INCH' O/S                | 11           | \$1,800.00 X         |
| 1PC  | FRONT KNUCKLE ARM O/S                        | 11           | \$1,815.42 X         |
| 1PC  | FRONT KNUCKLE ARM BEARING O/S                | 11           | \$680.00 X           |
| 1PC  | FRONT LOWER ARM O/S                          | 11           | \$845.00 X           |
|      |                                              | (102)        | \$22,142.42          |
|      | TO CHECK WIRING                              |              | \$50.00 20           |
|      | TO DISMANTLE & REPLACED FRONT PDC SENSOR     |              | \$80.00 30           |
|      | TO SPRAY RUST PROOFING                       | 11           | \$100.00 X           |
|      | TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE | 11           | \$280.00 X           |
|      | TO CONDUCT WHHEL ALIGNMENT                   | 11           | \$150.00 X           |
|      | TO RESET & REPROGRAMME SYSTEM                |              | \$100.00 80          |
|      | LABOUR FOR PANEL BEATING & REPLACED PARTS    |              | \$800.00 300         |
|      | TO PUTTY & SPRAY PAINTING                    |              | \$800.00 400         |
|      | TOTAL                                        |              | \$24,502.42          |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P-79.06.24  
102  
7115.60  
810  
7945.56