

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)** (LTS)
 CCPL
 Singapore
 LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	21/08/2024
Vehicle Reg. No.:	SHA9807E	Driveable?	NO
Party At Fault:	UNKNOWN		

Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	27/08/2020
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEKU389512	Chassis No:	KMHC851CVLU184468
Odometer:	0 KM		

Paint Type:
 List Item Discount: 20.00 %
 Total Loss? NO
 Est. Duration of Repair (day) 3

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS	Amount
Parts	2,409.04
Miscellaneous Items	12.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,241.04
+ GST 9.00% (S\$)	291.69
Nett Amount (S\$)	3,532.73

This claim is handled by: LIM TIEN SIONG

22/8 @ 13:49 hrs

REPAIR DETAILS

Reference

Lim Tien Siang

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Aug 2024)
 Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHA9807E/22/08/2024 13:49
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER / BR	20.00	0.00	*459.40 FL /
2	1		*REAR BUMPER REINFORCEMENT / BR	20.00	0.00	*394.80 FL /
3	2		*REAR BUMPER REINFORCEMENT BRKT RH / LH x nn	20.00	0.00	*276.20 FL
4	1		*REAR BUMPER CTR MOULDING / BR	20.00	0.00	*451.25 FL /
5	1		*REAR BUMPER LWR MOULDING x nn	20.00	0.00	*155.00 FL
6	10		*REAR BUMPER CLIPS / MC	20.00	0.00	*22.00 FL /
7	2		*REAR BUMPER REFLECTOR RH / LH x nn	20.00	0.00	*82.90 FL
8	2		*REAR BUMPER SIDE BRKT RH / LH x nn	20.00	0.00	*111.60 FL
9	1		*REAR BUMPER FOGLAMP / BR	20.00	0.00	*204.50 FL /
10	1		*REAR SMART KEY ANTENNA / BR	20.00	0.00	*40.50 FL /
11	2		*LICENCE PLATE LAMP RH / LH / BR / MS	20.00	0.00	*170.60 FL /
12	1		*REVERSE SENSORS / BR	0.00	0.00	*180.00 F /
13	2		*REAR FENDER ADV.STICKER RH / LH / MC	0.00	0.00	*200.00 F /
14	1		*REAR NO.PLATE WITH TRIM COVER / BR	0.00	0.00	*55.00 F /
15	1		*REAR BUMPER TOW COVER / BR	20.00	0.00	*98.80 FL /

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	2,902.55
- List Item Discount on L Items (S\$)	493.51
Total Parts (S\$)	2,409.04

ComfortDelGro Engineering Pte Ltd/SHA9807E/22/08/2024 13:49. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

1841.85
 -20%
 1473.48 + 435.00 nett = 1908.48

Estimates on Miscellaneous Items

Lim Tien Siong

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

12.00

Sub Total (\$\$)

12.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New 380 400.00

2 SPRAY PAINTING

New 280 300.00

3 R/I REVERSE SNSORS

New 20 120.00

692 Gross Labour Cost (\$\$)

820.00

ComfortDelGro Engineering Pte Ltd/SHA9807E/22/08/2024 13:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)

2600.48

23/8/24, 3.00pm

L/S - 2080.38

W/L

= 2100

L/S

By AL sy

2 d/s

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

