

SIN YU SIN WORKSHOP

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 417883

TO	: NTUC		
VEHICLE NO	: SMVS242X (2020)	2019 FEB	
VEHICLE MODEL	: TOYOTA COROLLA HYBRID		
CHASSIS NO	: JTDBB3BE10J028929		

Hui Rong

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Distorted</i>	1	\$ 657.60	\$ 657.60
2	FRONT BUMPER SIDE HOLDER <i>new</i>	1	\$ 68.20	\$ 68.20
3	FRONT BUMPER SPONGE <i>new</i>	1	\$ 168.80	\$ 168.80
4	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 398.90	\$ 398.90
5	FRONT BUMPER SIDE GARNISH <i>new</i>	1	\$ 69.80	\$ 69.80
6	HEADLAMP <i>cut</i>	1	\$ 3,557.10	\$ 3,557.10
7	FRONT FENDER <i>Distorted</i>	1	\$ 791.80	\$ 791.80
8	FRONT FENDER INNER SHIELD <i>torn</i>	1	\$ 188.70	\$ 188.70
9	FRONT FENDER EMBLEM <i>new</i>	1	\$ 69.60	\$ 69.60
10	BONNET <i>Distorted</i>	1	\$ 1,668.40	\$ 1,668.40
11	FRONT LOWER ARM <i>3 new</i>	1	\$ 805.10	\$ 805.10
12	FRONT SHOCK ABSORBER	1	\$ 787.60	\$ 787.60
13	FRONT KNUCKLE ARM	1	\$ 703.50	\$ 703.50
14	FRONT WHEEL HUB C/W BEARING <i>new</i>	1	\$ 709.60	\$ 709.60

TOTAL PRICE: \$ 10,644.70
LESS 25% \$ 2,661.17
SUB TOTAL PRICE: \$ 7,983.53

6933.20
5199.80

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS <i>3 new</i>	1 SET	\$ 30.00	\$ 30.00
2	FRONT FENDER INNER SHIELD CLIPS	1 SET	\$ 30.00	\$ 30.00
3	FRONT WHEEL RIM <i>new</i>	1	\$ 800.00	\$ 800.00
4	FRONT WHEEL RIM COVER <i>cut</i>	1	\$ 180.00	\$ 180.00
5	FRONT TYRE <i>new</i>	1	\$ 280.00	\$ 280.00

TOTAL : \$ 1,320.00

240

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	<i>600</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>600</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>x</i>	
5	TO REMOVE FRONT UNDERCARRIAGE	\$ 300.00	<i>x</i>	
6	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80</i>	

TOTAL: \$ 2,650.00

1310

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,303.53
TOTAL LABOUR COST: \$ 2,650.00
TOTAL REPAIR COST: \$ 11,953.53

Total: 6749.90
A/S: 5.4K.
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TYPE OF ACCIDENT : 13/08/2012
DATE OF ACCIDENT : 30/08/2012
MODEL : 2200CC/1000
VEHICLE NO : 2200CC/1000
ID : 2200CC/1000