

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO.: /20240402/0838	3	LOCATION OF FIRE: Open Carpark lot 302, in front of	
FIRE REPORTED ON: 02 April 2	024		
TIME OF CALL: 16:31:52 hrs		Block 71 Circuit R Singapore 370071	
STATION COVERAGE: Kallang Fire Station	١		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine compartment of a Nissan van (GBF4640X).			
METHOD OF EXTINGUISHMENT: By SCDF crew using a hose reel jet and a hose line water jet from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE OBSERVED*: As a result of the fire, the engine compartment of the van was damaged. Other parts of the van sustained varying degrees of heat, smoke and water damage.			
An adjacent parked Mazda car (SNN7489M) sustained varying degrees of heat, smoke and water damage.			
3. FATALITY/INJURY INFORMATION			
NAME	NRIC/FIN		DEAD/INJURIES SUSTAINED
NIL	N	IL	NIL
REPORT ISSUED BY: ANG LI FENG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated report. No signature is required.

^{*}This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.