

Date: 19-8-2024
Vehicle No: SMP2207U
Model: MERCEDES BENZ S300L
Chassis: WDD2211542A434904
Reg.Year: 24.11.2011

*Not with the
1/15/2024 83350/h
2 day*

Third Party Insurer: FCIL
Third Party Veh No: SHB5813H
Date of Accident: 14/08/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		2,100.00
2	REAR REVERSE SENSOR	2	\$300.00	\$600.00
3	REAR LH BUMPER RETAINER	1		\$110.00
4	REAR BUMPER REINFORCEMENT	1		\$850.00
5	REAR END PANEL	1		REPAIR
6	REAR BOOT	1		REPAIR
SUB TOTAL				\$3,660.00
LESS 10%				-\$366.00
PARTS TOTAL				\$3,294.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		\$50.00
2	REAR REVERSE SENSOR MOUNTING BRACKET	1		\$350.00
S/N TOTAL				\$400.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL & ETC.

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

TO DIAGNOSTIC AND RESET RADAR SENSOR FAULT CODE

TO CHECK WIRING & ELECTRICAL SYSTEM.

229
\$600.00

259
\$800.00

601
\$100.00

225
\$250.00

151
\$100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

LABOUR TOTAL \$1,850.00

TOTAL \$5,544.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 3 Singapore 554500
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 3-9-2024
Vehicle No: SMP2207U
Model: MERCEDES BENZ S300L
Chassis: WDD2211542A434904
Reg. Year: 24.11.2011

Third Party Insurer: FCIL
Third Party Veh No: SHB5813H
Date of Accident: 14/08/2024
Estimator: Loong
Surveyor:

SUPPLEMENTARY ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR LH BOOT SILL COVER	1	mg cut	\$100.00
2	REAR RH BOOT SILL COVER	1		\$100.00
SUB TOTAL				\$200.00
LESS 10%				-\$20.00
PARTS TOTAL				\$180.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOT SILL COVER CLIPS SET	1		\$80.00
S/N TOTAL				\$80.00

Finalize:

Parts = \$ 3375.00
Nett = \$ 280.00
Labor = \$ 545.00

Unsummed 4200.00 -20%
= \$ 3360.00 ⇒ \$ 3400.00