

Your Ref : N/A

Date: 06th Sep 2024

Our Ref : CS/III24080526/Uvp3e2

M/s India International Insurance Pte Ltd

64 Cecil Street

#05-02 IOB Building

Singapore 049711

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJT 2094S
INSURED VEHICLE: SMY 911K
ACCIDENT ON 30/08/2024**

Instruction was received to inspect the vehicle Reg. No. SJT 2094S. The inspection was conducted on 30/08/2024 at the premises of M/s Precise Auto Service, No.1 Kaki Bukit Ave 6 #02-34/36, Singapore 417883.

The following vehicle information was recorded:

Registration Number	: SJT 2094S
Make/Model	: Toyota Corolla Altis 1.6 Auto
Year of Registration	: 2009
Body Colour	: Black
Chassis Number	: MR053ZEE106154739
Engine Capacity	: 1598 cc

The vehicle sustained damages at the rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 1,200.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 237.00
Nett Liability	<u>S\$ 963.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.