

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: LIH/ta2/sn/1184623.ECICS Date: 06th Sep 2024

Our Ref: CS1/LAW24080405/Dnp3e2

M/s ECICS Ltd

C/o Legal Solutions LLC 80 Raffles Place #44-05 UOB Plaza Singapore 048624

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMD 1344B INSURED VEHICLE: SLP 6062E ACCIDENT DATE: 07/05/2023

We thank you for your instruction on 23/08/2024.

We acknowledge receipt of the following documents:-

- Automobile Inspection Report of SMD 1344B from M/s Absolute Appraisal Services Pte Ltd.
- b) Final Repair Bill of SMD 1344B from M/s Nexwave Auto.
- c) Singapore Accident Statement and Police Report of Vehicles SMD 1344B.
- d) Colour damaged vehicle photographs of SMD 1344B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMB 1344B

Make & Model : Toyota Lexus IS250 (A) Chassis Number : JTHBK262305087062

Year of Registration : 2008 Engine Capacity : 2500 cc

- 2. We recommend that the repairs of the entire damage require about <u>10 (Ten)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.