



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400307W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNH8528J

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#22-00
SINGAPORE 048580
63476100

WIP No 20280
Reg No/Reg Date SNH8528J / 30/11/2022
Date In/Mileage / 0
Chassis No W1K1183842N3510487
Engine No 28291480916282
Make/Model MB/CLA 180 COUPE
Colour/Trim 021 191 Cosmos Blac/ 041 111 ARTICO Leat

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator	
WI000576	Credit	04/10/2024/ 09:54	VS	356 / Vincent Seah	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE :5140148424//16.08.2024
DRIVE IN/EXCESS :20.08.2024// TP CAR NO.: SLL8606U-INDIA
DATE IN/DATE SURVEY:04.10.2024 //
DIRECT SETTLEMENT: YAN -LKK

M BPNSUN

SUDRIES

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

TRANSFER REAR BOOT MECHANISM TO NEW PANEL

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. 960 x 1.5

A BPIRES

RESPRAY ON REAR BUMPER, BOOT AND ACCIDENT AFFECTED AREA 800 x 2

A BPILAB

TRANSFER REAR BOOT SPOILER TO NEW PANEL NETT

M REAR BUMPER

M REAR LOWER BUMPER

R TRUNK LID

R MODEL PLATE

M RELEASE HANDLE

M MERCEDES STAR

1.00	1463.03	00.00	1463.03
1.00	517.32	00.00	517.32
1.00	2354.89	00.00	2354.89
1.00	224.29	00.00	224.29
1.00	199.60	00.00	199.60
1.00	186.88	00.00	186.88

Steve (LKK) +6 010 9479541

4/10/24, 11.00am

m p/p

Confirmed & accepted by

by Bob Smy

5 days

sterchen@lkk auto. com

9% GST on 10621.01 955.89

Total Payable 11,576.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 120378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Page 1 of 1