



FALCON - AIR

ANG JIT HOCK @ SAID ALWI ANG
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE
575721

Tel : 96743764

*Not authorized
11 Sep @ 2950h
Resurvey After Paint
4 days*

Estimate : ES000095
Date : 28/08/2024
Vehicle No. : SLU5390M
Vehicle Model : TOYOTA ALTIS ELEGANCE
Chassis No. : MR053REH604576003
Accident Date : 26/08/2024
Claim No. :
Reference : TP GEG AGT MINDEF
Policy No. : V5010280
Page : 1 of 2

Item	Qty	Description	Unit Price S\$	Amount S\$
1.	1	RH HEADLAMP	<i>sn</i> 1,408.00	1,408.00 X
2.	1	FRONT BUMPER	<i>n</i> 523.00	523.00 X
3.	1	RH FRONT BUMPER SIDE RETAINER	<i>sn</i> 68.00	68.00 X
4.	1	RH FRONT FENDER	<i>sn</i> 675.00	675.00 ✓
5.	1	RH FRONT FENDER EMBLEM	<i>na</i> 62.00	62.00 ✓
6.	1	RH FRONT FENDER INNER SHIELD	<i>sn</i> 208.00	208.00 X
7.	1	RH SIDE MIRROR ASSY	<i>cm</i> 899.00	899.00 ✓
8.	1	RH FRONT DOOR	<i>n</i> 1,263.00	1,263.00 X
9.	2	RH FRONT DOOR HINGE	<i>n</i> 107.00	214.00 X
10.	1	RH FRONT DOOR BLACK STICKER	<i>na na</i> 88.00	88.00 X
11.	1	RH FRONT RIM	<i>pd/sn</i> 1,728.00	1,728.00 ✓
12.	1	RH FRONT TYRE	<i>sn</i> 280.00	280.00 X
13.	1	RH FRONT WHEEL BEARING	189.00	<i>sn</i> 189.00 X
		Discount 25 %		-1,901.25
		SubTotal		5,703.75
14.	1	FRONT BUMPER CLIP	<i>na</i> 60.00 X	60.00
15.	1	RH FRONT FENDER INNER SHIELD CLIP	<i>na</i> 60.00	60.00
16.	1	TO CHECK WIRING AND FOCUS HEADLAMP	50.00	<i>201</i> 50.00
17.	1	TO REMOVE/REFIX RH FRONT DOOR MECHANISM	<i>na</i> 100.00 X	100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Sin Ming Autocare S(575721) Pte Ltd)

Continue to Next Page

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

ANG JIT HOCK @ SAID ALWI ANG
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE
575721

Tel : 96743764

Estimate : **ES000095**
Date : 28/08/2024
Vehicle No. : SLU5390M
Vehicle Model : TOYOTA ALTIS ELEGANCE
Chassis No. : MR053REH604576003
Accident Date : 26/08/2024
Claim No. :
Reference : TP GEG AGT MINDEF
Policy No. : V5010280
Page : 2 of 2

Item	Qty	Description	Unit Price S\$	Amount S\$
18.	1	COMPUTERISE WHEEL ALIGNMENT	120.00	<i>600</i> 120.00
19.	1	TO REMOVE/REFIT TYRE TO NEW RIM AND BALANCING	50.00	<i>200</i> 50.00
20.	1	TO REMOVE NECESSARY PARTS, TO REPAIR INNER PANEL, REPLACE DAMAGE PARTS AND ALIGN THE SAME	600.00	<i>400</i> 600.00
21.	1	TO PUTTY AND RESPRAY FRONT BUMPER, RH FRONT FENDER, RH FRONT DOOR	700.00	<i>650</i> 700.00

SINGAPORE DOLLAR EIGHT THOUSAND ONE HUNDRED THIRTEEN AND CENTS SIXTY NINE ONLY

Total **S\$** **7,443.75**

Notes :

- All cheques should be crossed and made payable to FALCON-AIR AUTO SERVICES PTE LTD
- Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

Accepted by

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg