



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24080419/Rqh3e2(N) Date: 09/01/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 3403X	Veh. Inspected	SMT 6686Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS24/2630	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	23/08/2024
2. Vehicle Particulars & Condition				
	Make & Model	PEUGEOT RCZ 1.6 TURBO A	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	VF34J5FVABP013923	Colour	WHITE
	Odometer	149352 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/40Z R19	MICHELIN	6 mm
	L/H Front Tyre	235/40Z R19	MICHELIN	6 mm
	R/H Rear Tyre	235/40Z R19	MICHELIN	6 mm
	L/H Rear Tyre	235/40Z R19	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/08/2024	Inspection Date	26/08/2024
	Survey held at	TECHNIK AUTOLAB PTE LTD 1 CORPORATION DRIVE, #04-04, SINGAPORE 619775		
5a. Remarks				
	A)REGISTRATION DATE: 08 NOV 2011 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	