

Estimate Repair For Vehicle FBK 3400 C (Yamaha FZN150)

QTY	DESCRIPTION OF PARTS		PRICE	
1 pc	Handle bar / BT	\$	140.00	/
1 set	Handle bar balancer L/R / cut	\$	24.00	/
1 set	View mirror L.H / cut	\$	150.00	70 /
1 pc	Headlamp cover upper / BR	\$	58.00	/
1 pc	Front air guide cover L.H / cut	\$	58.00	/
1 pc	Front signal lamp L.H X nn	\$	38.00	
1 pc	Front fender / cut	\$	185.00	130 /
1 pc	Front footrest L.H / cut	\$	45.00	/
1 pc	Gear shift pedal / BT	\$	65.00	/
1 pc	Rear mudguard / BR	\$	215.00	180 /
1 pc	Rear mudguard stay / BR	\$	30.00	/
1 pc	Rear mudguard reflector X nn	\$	12.00	
1 pc	Rear tail lamp / cut	\$	150.00	/
1 pc	Rear tail cover X nn	\$	25.00	
1 2 pcs	Rear signal lamp L/R \$ 38.00 (RH) / cut	\$	76.00	38 /
1 pc	Rear running chain guard / cut	\$	115.00	/
1 pc	Rear exhaust muffler protector (Black) / cut	\$	80.00	/
1 pc	Rear exhaust muffler protector (Silver) / cut	\$	55.00	/
		\$	1,521.00	1238
	Less 10%	\$	152.10	-10%
		\$	1,368.90	1114.20
	S/NETT ITEM			
1 set	Engine crash bar L/R / BT / cut	\$	340.00	250 /
1 set	Front & rear number plate / BT	\$	35.00	/
1 pc	Rear box bracket X R	\$	280.00	
		\$	2,023.90	285
	Labour charge			
1]	Transportation (2 Trips)	\$	80.00	60
2]	Front fork & steering stem alignment.	\$	180.00	150
3]	Replace, realign & adjust above damaged parts. check wiring, re-connection & lighting system.	\$	350.00	300
	Sub Total :	\$	610.00	510

Steve (LKK)
28/8/24, 10.30am
w ll
L/S
ly SL y
3 days
Jiml rpr 2K

Total Parts and Labour \$ 2,633.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

1909.20
L/S - 1527.36
= 1550