

44425 - C00001

SERVICE ESTIMATE

SL: SERVICE SALES - PC

Digo Corporation Pte. Ltd.

54 Senoko Road

Woodlands East Industrial Estate

Singapore 758118

GST Reg.No:M28920628X

Inv.No. : B&P

0 Page 1

Inv.date. : 27/08/2024

WIP No. : 20842

Veh.In/Out:

*Tel.No. : Mobile: 869988878

Reg.No. : SGN8878A

Reg.date. : 25/09/2020

Mileage : 0

Chassis No: SJAAB14V5MC032829

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Digo Corporation Pte

Op.No	Description	Mech Qty	Price	Disc%	Pkg Amount	G
NOTES	NOTES (CTI TP)	0	0.00	0		S
802	TO REPLACE RR BUMPER, RR BUMPER CHROME MLDG LH/RH, TAILGATE BADGE.	0	7600.00	0	7,600.00	S
					3800	
800	TO RH QTR PANEL, TAILGATE TO BLEND & SPRAY PAINT TAILGATE, RR BUMPER, RH QTR PANEL	0	6000.00	0	6,000.00	S
					5000	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	1020.00	0	1,020.00	S
	BADGE (SELF-ADHESIVE	1.0 EA	156.00		156.00	S
	'BENTLEY WINGS' EMBL	1.0 EA	340.20		340.20	S
	TRIM FOR BUMPER RR LH	1.0 EA	814.70		814.70	S
	TRIM FOR BUMPER RR RH	1.0 EA	814.70		814.70	S
	BUMPER COVER PRIMED	1.0 EA	9504.00		9,504.00	S
	MOUNTING FOR BUMPER	1.0 EA	372.60		372.60	S
					140.40	
					223.02	
					733.23	
					733.23	
					8553.60	
					335.34	

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T 6430 4700 www.wearnes.com

Co reg no. 199501400R / GST reg no. M28920628X

44425 - C00001

Digo Corporation Pte. Ltd.
54 Senoko Road
Woodlands East Industrial Estate
Singapore 758118SERVICE
SL: SERVICE SALES - PC
ESTIMATEGST Reg.No:M28920628X
B&P
0 Page 2Inv.No. : 27/08/2024
Inv.date. : 20842
WIP No. : 20842Veh.In/Out:
*Tel.No. : Mobile: 869988878Reg.No. : SGN8878A
Reg.date. : 25/09/2020
Mileage : 0

Chassis No: SJAAB14V5MC032829

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Digo Corporation Pte

Op.No	Description	Mech Qty	Price	Disc%	Pkg Amount	G
	MOUNTING FOR BUMPER	1.0 EA	372.60		372.60	S
	RETAINER FOR ULTRASO	1.0 EA	96.00		96.00	S
	RETAINER FOR ULTRASO	1.0 EA	96.00		96.00	S
	RETAINER FOR ULTRASO	1.0 EA	113.40		113.40	S
	RETAINER FOR ULTRASO	1.0 EA	113.40		113.40	S
	RETAINER FOR ULTRASO	1.0 EA	113.40		113.40	S
	RETAINER FOR ULTRASO	1.0 EA	113.40		113.40	S
	SEAL RING SATIN BLAC	6.0 EA	10.10		60.60	S

Rasul
4 days
04/09/24
Reg 64 part

Labour Total	14,620.00	Gross Total.	27,701.00
Parts Total	13,081.00		
Package Total	0.00		
		Net.....	27,701.00
		GST @ 9.0%	2,493.09
		Total.....	30,194.10
		Paid.....	0.00
		Please Pay..	30,194.10
		PreviousRate	

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: