

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/LPC24080440/49h3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE 6375T

at Workshop m/s hup lion huat

of _____

Insured: XE 7892K

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$45K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C363W

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 3870

Veh No: XE 6375T Yr Regn: 25/05/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: m/f Fuso FUS-1 c.c 11967

Colour: white / blue A/C: Insured / Std / NI / NA

Sp. Reading: 145364 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FV 5155A 20025

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295 / R 22.5

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HILLO

Front 6 mm Rear 6/6 6/6

R/Bal. 6 mm R/Bal. 6/6 6/6

L/Bal. 6 mm L/Bal. 6/6 6/6

D.O.A. 25/08/24 D.O.I. 29/8/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R/L, R/L not checked

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 22/25K

3/9/24 1/5 @ 2000 hrs; inland s.hui (Red #11748.39, 59%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 22/9 2000 : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$) S + RS, \$I☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$) TOTAL

Report Format : TP

Lump Sum / I.B.I: (\$ 8000)

Survey Fee:

Transportation:

TOTAL

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO:201327339E

not Authorized
 in
 motor
 29/8/24
 d/s # 8000/
 4 days.
 myphatary.

M/S : Lonpac Insurance Bhd
 300 Beach Road
 #17-04/07 The Concourse,
 Singapore 199555

TEL: 6250 7388 (ext: 254) FAX: 6296 2706
 ATTN: Motor Claim Department \ 6546 5886

Estimate No: ES1602146
 Date: 25 Aug 2024
 Policy No: DMCG24008447
 Veh Reg No: XE6375T
 Make/Model: MITSUBISHI FUSO
 FV51SS3VDEA
 Chassis No: FV51SSA20025
 Engine No: OM457LA457972C032609
 Reg. Date: 25/05/2016

Your Ref No: FELICITY ENG PL
 Claim Type: Third Party
 Accident Date: 25/08/2024
 TP Veh Reg No: XE7892K

Estimate Repair Cost to Vehicle No :XE6375T

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 Front Windscreen Glass	1,680.05	1 PC one	1,680.05	✓
2 Front Windscreen Glass Rubber Seal	670.89	1 PC Cu	670.89	✓
3 Wiper Blade	66.74	1 PC 17	66.74	X
4 Front Corner Panel -LH	468.21	1 PC 12	468.21	X
5 Front Corner Panel Bracket -LH	107.00	1 PC 17	107.00	X
6 Front Corner Panel Lower Bracket -LH	32.78	1 PC 17	32.78	X
7 Front Corner Panel Signal Lamp -LH	195.03	1 PC 17	195.03	X
8 Front Corner Panel Bottom Rubber Seal -LH	84.23	1 PC 17	84.23	X
9 Front Bumper	2,259.31	1 PC Dis	2,259.31	✓
10 Front Bumper Cover -LH	305.89	1 PC Dis	305.89	✓
11 Front Bumper Side -LH	140.29	1 PC Dis	140.29	✓
12 Front Bumper Step Garnish	217.26	1 PC Dis	217.26	✓
13 Front Bumper Lower Stay	169.07	1 PC 3rd	169.07	✓
14 Front Bumper Bracket	37.30	1 PC Dis	37.30	✓
15 Front Bumper Side Air Dust -LH	96.70	1 PC Dis	96.70	✓
16 Front Top Bumper	273.12	1 PC 17	273.12	X
17 Front Top Bumper Reinforcement	884.79	1 PC Dis	884.79	✓
18 Front Top Bumper -LH	193.04	1 PC Dis	193.04	✓
19 Front Top Bumper Reinforcement -LH	226.06	1 PC Dis	226.06	✓
20 Front Headlamp Assy -LH	1,286.45	1 PC one	1,286.45	✓
21 Front Headlamp Rim -LH	181.18	1 PC one	181.18	✓
22 Front Headlamp Aluminium Bracket -LH	947.63	1 PC 17	947.63	✓
23 Front Fog Lamp Assy -LH	293.25	1 PC 17	293.25	X
24 Front Fog Lamp Rim -LH	186.05	1 PC one	186.05	✓
25 Front Door Assy -LH	5,542.30	1 PC 12	5,542.30	X
26 Side Mirror Stay Upper -LH	316.31	1 PC 17	316.31	X
27 Side Mirror Stay Upper Bracket -LH	128.30	1 PC 17	128.30	X
28 Side Mirror Stay Bar Lower -LH	108.94	1 PC 17	108.94	X
29 Side Mirror Stay Bar Lower Bracket -LH	130.16	1 PC 17	130.16	X
30 Side Mirror Lower Stay Bar -LH	140.16	1 PC 17	140.16	X
31 Side Mirror Stay -LH	817.09	1 PC 3rd	817.09	✓
32 Side Mirror Stay Bracket -LH	354.12	1 PC 3rd	354.12	✓
33 Side Mirror (Big) -LH	177.68	1 PC 17	177.68	X
34 Side Mirror (Square) -LH	159.83	1 PC one	159.83	✓
35 Side Mirror (Round) -LH	107.24	1 PC 17	107.24	X

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9 , Singapore 539278
 TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
 GST:52832105J RCB NO.201327339E

M/S : Lonpac Insurance Bhd
 300 Beach Road
 #17-04/07 The Concourse ,
 Singapore 199555

TEL: 6250 7388 (ext: 254) FAX: 6296 2706
 ATTN: Motor Claim Department \ 6546 5886

Your Ref No: FELICITY ENG PL
 Claim Type: Third Party
 Accident Date: 25/08/2024
 TP Veh Reg No: XE7892K

Estimate No: ES1602146
 Date: 25 Aug 2024
 Policy No: DMCG24008447
 Veh Reg No: XE6375T
 Make/Model: MITSUBISHI FUSO
 FV51SS3VDEA
 Chassis No: FV51SSA20025
 Engine No: OM457LA457972C032609
 Reg. Date: 25/05/2016

Estimate Repair Cost to Vehicle No :XE6375T

Description	U/Price	Quantity	List Price S\$	Amount S\$
			18,984.45	
		Less 25%	4,746.11	14,238.39
Labour				
36 To remove & refit front windscreen glass ,rubber seal , iu bracket .	200.00	1 -	200.00 ✓	
37 To remove & refit front LH door & realightment ,etc .	280.00	1 -	280.00 X	
38 To remove & refit headlamp cable ,system & check wiring & refocus all light .	230.00	1 -	230.00 30	
39 Labour charge to cut & weld & dismantle & remove & refit all above parts .	2,500.00	1 -	2,500.00 1000	
40 To spray & painting all accident affected arera .	2,300.00	1 -	2,300.00 800	
			5,510.00	5,510.00
Total				S\$ 19,748.39
Add GST @ 9%				1,777.36
Total Amount Payable				S\$ 21,525.75

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND FIVE HUNDRED TWENTY FIVE AND CENTS SEVENTY FIVE ONLY

For HUP LIAN HUAT ENGINEERING
WORKS

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts, before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AUTHORISED SIGNATURE

P-10 M3
 252
 8109.75
 1930
 10039.75
 22
 8000

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	363W
Vehicle Details	
Vehicle No.:	XE6375T
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Aug 2024
Vehicle Make:	MITSUBISHI
Vehicle Model:	FUSO FV51SS3VDEA
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	OM457LA457972C0326097
Chassis No.:	FV51SSA20025
Maximum Power Output:	-
Open Market Value:	\$99,394.00
Original Registration Date:	25 May 2016
First Registration Date:	25 May 2016
Transfer Count:	2
Actual ARF Paid:	\$4,970.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,817.00
COE Rebate Amount:	\$3,870.00
Total Rebate Amount:	\$3,870.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 29 Aug 2024

OK

Post an Advertisement

Sell it yourself! Advertise it at just **\$72 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Low Interest Rate In-House Loan by GV Cars Financing



Promotional 3.28% COE CARS

loan by GV CARS FINANCING

GV Automobile

Centre: StarAd

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.



Sort by

Date Posted

20

r

5 vehicles

Mitsubishi Fuso FV51

Basic Search

Search

Price

Any price

Depre

Any depre

Reg Date

Any date

Eng Cap

Any

Veh Type

All types

Fuel

Any fuel

Mileage

Any

OMV

Any

Gear

Any Gear

Past Owners

Any

Category

All categories

Scheme

All schemes

Dealer

Any Dealer

Location

Any

Status

Available

Make & Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	St
 Mitsubishi Fuso Super Great FV51S (New 10-yr COE) Fuel Type: Diesel Posted: 28-Aug-2024	\$149,600	\$14,950 /yr	24-Oct-2014	11,967 cc	-	Truck	A
 Mitsubishi Fuso Super Great FV51S (New 10-yr COE) Fuel Type: Diesel Cheapest 28 Ton Truck With Crane! Low mileage! (Max Boom Length 10.10m, Safe Working Load 5,200kg) Comes with crane remote control and 2x new remote batteries! Over \$5K wear & tear done up with invoice to prove! Previous... Net Link Partners Pte Ltd Posted: 22-Aug-2024	\$152,888	\$15,280 /yr	28-Nov-2014	11,967 cc	107,000 km	Truck	A
 Mitsubishi Fuso Super Great FV51S (New 10-yr COE) Fuel Type: Diesel Palfinger PK-50002 crane high performance, new paint work with crane service all done, and also buy back guarantee! After COE ends. High loan packages available. Net Link Partners Pte Ltd Posted: 22-Aug-2024	\$218,800	\$21,870 /yr	29-Apr-2015	11,967 cc	-	Truck	A
 Mitsubishi Fuso Super Great FV51S Fuel Type: Diesel Low mileage done hooklift with PK19502 crane! Excellent condition! See to believe. Flexible bank and in house loan available. Convince Auto Posted: 16-Aug-2024	\$118,800	\$91,290 /yr	18-Dec-2015	11,967 cc	32,256 km	Truck	A
 Ralliart Automotive Foot Pedals BRAND NEW set of Ralliart Auto & Manual Pedals! CHEAPEST IN SG GUARANTEED! Click NOW to find out more! More info about this product Compare							

https://www.sgcarmart.com/used_cars/listing.php?MOD=Mitsubishi+Fuso+FV51&ASL=1&PR1=0&PR2=&DP1=0&DP2=&FR=Any&TO=Any&ENG... 1/2