



Your Ref : D24007438MFCT

Date: 13th Sep 2024

Our Ref : CS/FCI24080441/Unp3e2

M/s MS First Capital Insurance Ltd

16 Raffles Quay

#42-01 Hong Leong Building

Singapore 048581

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO. FBK 3803Z
INSURED VEHICLE NO. SHC 8857G
ACCIDENT ON 21/08/2024**

Instruction was received to inspect the vehicle Reg. No. FBK 3803Z. The inspection was conducted on 27/08/2024 at the premises of M/s Erofia Motor Trading Pte Ltd, 1 Kaki Bukit Avenue 6 #02-62 Autobay @ Kaki Bukit, Singapore 417883.

The following vehicle information was recorded:

Registration Number	: FBK 3803Z
Make/Model	: Daelim Daystar 250
Year of Registration	: 2015
Body Colour	: Purple / Multi Colour
Chassis Number	: KMYBZ2BLSEC000371
Engine Capacity	: 247 cc

The vehicle sustained damages at the rear portion and n/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 2,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 621.00)
Nett Liability	<u>S\$ 1,379.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.