

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC1871K
Accident Date : 25-Aug-2024

Our Ref : 024167 (FIRST) / CHAN

TONG JIN SHI JULIA
464B CLEMENTI AVE 1
#12-48
Singapore 122464

No. : 07146

Date : 26-Aug-2024

PAGE : 1

NOT Withheld
CLP @ 1700.
Repair After Paint
2 days

ESTIMATED COST OF REPAIR FOR AUDI A3 SNM7965K

1 pc Front n/s door glass
1 pc Front n/s door mirror assy
1 pc Front n/s door mirror lamp
1 pc Front n/s door mirror cover
1 pc Front n/s door mirror casing
1 pc Front n/s door mirror glass
1 pc Front n/s door outer moulding

<i>GL</i> GMA	180.00	—
<i>GL</i> GL	780.00	—
<i>GL</i> GL	75.00	—
<i>GL</i> GL	130.00	—
<i>GL</i> GL	80.00	—
<i>GL</i> GL	790.00	—
<i>GL</i> GL	190.00	X

2,225.00

Less 10% : 222.50

1 pc Frt n/s door glass solar film

To putty and spray replaced parts

To remove door board for renew door
mirror and door belt, door glass

2,002.50 *GL*
GL 80.00 *sn*

300.00 *GL*

250.00 *150L*

Total : S\$ 2,632.50

Singapore Dollars Two Thousand Six Hundred and
Thirty Two and Cents Fifty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: