

TTS EUROCARS PTE LTD

2 DEFU SOUTH STREET 1, #04-04 DEFU INDUSTRIAL CITY

Date : 26/8/2024

RE: VEHICLE REPAIR QUOTATION

Vehicle Reg No
 Name of Insured
 Policy Number
 Date of Accident
 Tyre of Claim
 Model
 Chassis No

ms + Andrew
 27/8/24
 2/5 @ 2500
 4 days
 1 whole day
 1/2 day

SCU1000Y

TAY LEE LING Signature:

P10431239R03 Date:

23/8/2024

THIRD PARTY CLAIM

TOYOTA WISH

JTDGG20W50J004937

LKK Auto Consultants hence notify
 the Repairer of the following:

- To rectify before/after spray painting
- To display damaged parts before rectify
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reapproved and is subject to final approval from Insurance Company

Acknowledged by Repairer

We are please to submit our estimate of repairs to the above mention vehicle.

PARTS COST

		QTY	UNIT/PC	Parts
1	REAR TAILGATE R	1	\$2,316.20	\$2,316.20 X
2	REAR TAILGATE EMBLEM SUC	1	\$80.20	\$80.20 X
3	REAR TAILGATE HINGE RH ^ ^	1	\$104.10	\$104.10 X
4	REAR TAILGATE HINGE LH ^ ^	1	\$104.10	\$104.10 X
5	REAR TAILGATR INNER PULL GARNISH ^ ^	1	\$95.20	\$95.20 X
6	REAR TAILGATE INNER TRIM GARNISH ^ ^	1	\$593.60	\$593.60 X
7	REAR TAILGATE MECHANISM LOCK SUC	1	\$660.00	\$660.00 X
8	RR TAILGATE MECHANISM LOCK STRIK ^ ^	1	\$67.80	\$67.80 X
9	RR TAILGATE ANTENNA SENSOR One 39160	1	\$486.60	\$486.60 ✓
10	RR TAILGATE OUTER GARNISH ^ ^	1	\$494.30	\$494.30 X
11	RR TAILGATE RUBBER GUIDE STOPPER ^ ^	2	\$37.30	\$74.60 X
12	RR TAILGATE WEATHERSTRIP ^ ^	1	\$456.60	\$456.60 X
13	END PANEL 20/24 902.80	1	\$951.70	\$951.70 ✓
14	REAR BUMPER 20/24 831.50	1	\$994.50	\$994.50 ✓
15	REAR BUMPER CLIPS neu	12	\$5.70	\$68.40 ✓
16	REAR BUMPER SIDE RETAINERS ^ ^	2	\$246.10	\$492.20 X
17	REAR BUMPER REINFORCEMENT NS	1	\$650.50	\$650.50 X
18	REAR BUMPER REFLECTORS ^ ^	2	\$81.70	\$163.40 X
19	REAR BUMPER REVERSE SENSOR SUC	2	\$550.00	\$1,100.00 X
				\$9,954.00
	LESS 25%			-\$2,488.50
				\$7,465.50

LABOUR

1	TO DISMANTLE & REFIX REAR SENSOR	\$300.00 30
2	TO CHECK TAILLAMP WIRING SYSTEM & FUNCTION ETC.	\$250.00 20
3	TO APPY TUFF COATING FOR AFFECT	\$300.00 30
4	TO PANEL BEATING, DISMANTLE & REFIX REAR TAILGATE, END PANEL REAR BUMPER AND ALL NECESSARY ETC.	\$2,500.00 800
5	TO SPRAY PAINTING ON REAR TAILGATE REAR BUMPER AND ALL NECESSARY ETC.	\$2,200.00 600

\$13,015.50

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

2-2194.30
 252
 1648.72