

(08/11/13) wef

ASS. REC. BY:

REF: CS/A1424080456/Rvp³

3617

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDD 6608P

at Workshop m/s Premium

of B6001 SEUM

Insured:

Bih

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)

3800

Make of Veh:

(Policy Condition)

3pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

207K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDD 6608P

Yr Regn:

2022 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

AUDI A6 DESIGN 2.0 TFSI

cc 1984

Colour

BLACK

AC: Insured / Std / NI / NA

Sp. Reading

31114

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAM 222F23NN031079

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

u.

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/08/24

D.O.I.

28/08/24

Survey held at

B6001

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 73K

We will be advising our principal a cost of repair of \$38,252.08 before excess \$3,800.00 & GST with 11 days of repair

(red. \$22334.92, 36%)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 11

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

Site Insp (\$

S + RS \$

Interview (\$

Photos

Tech. Invs (\$

Others

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0639/2024/KS
DATE : 28-Aug-24
WIP : 28740

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR TAN AIK PING
ADDRESS : 146 QUEEN'S AVENUE
SINGAPORE 758600
TELEPHONE : HP +65 93630405
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220129564
VEHICLE NO : **SDD 6608 P**
MODEL CODE : A6 DESIGN 2.0 TFSI S TRONIC
MODEL YEAR : 11/11/2022
ENGINE NO : DKY 016762
CHASSIS NO : WAUZZZF23NN031079
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Aug-24
PLACE OF ACCIDENT : SENTOSA GATEWAY TOWARDS TELOK BLANGAH RD
BEFORE UNDERPASS



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDD 6608 P.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 /	
3	TO REMOVE AND REINSTALL RHS WING MIRROR TO FACILTATE DOOR PAINTING.	S/N \$ 280.00 /	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,500.00 /	1750
5	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET AND RHS FRONT DOOR.	\$ 6,400.00 /	2750
6	TO CARRY OUT 360 DEGREE CAMERA CALIBRATION WITH VAS TOOLS.	S/N \$ 800.00 /	
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 292.00 /	
TOTAL LABOUR CHARGES		: \$ 15,552.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 6608 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER tom ✓	1	\$	3,380.00
2	FRONT BUMPER FIXING PARTS X	1	\$	696.00
3	FRONT BUMPER PLATE H? ✓	1	\$	54.00
4	FRONT BUMPER CLOSING ELEMENT - CENTER can? ✓	1	\$	279.00
5	FRONT BUMPER ADAPTOR - LH / RH ?	2	\$	100.00
6	FRONT BUMPER REINFORCEMENT BRACKET - RH ?	1	\$	140.00
7	FRONT BUMPER GRILLE - LOWER CENTRE can ✓	1	\$	192.00
8	FRONT BUMPER CLOSING ELEMENT - LOWER can ✓	1	\$	263.00
9	FRONT BUMPER SPOILER ?	1	\$	316.00
10	FRONT BUMPER AIR GUIDE GRILLE - RH MIP ✓	1	\$	544.00
11	FRONT BUMPER AIR GUIDE - RH INNER ?	1	\$	42.00
12	FRONT BUMPER AIR GUIDE - RH OUTER ?	1	\$	33.00
13	RADIATOR GRILLE can ✓	1	\$	2,725.00
14	RADIATOR GRILLE COVER ?	1	\$	72.00
15	"360" DEGREE CAMERA COVER X	1	\$	65.00
16	"360" DEGREE CAMERA BRACKET X	1	\$	116.00
17	FRONT PARKING AID SENSOR MIP ✓	1 2	\$	629.00
18	FRONT SIDE ASSIST PARKING AID SENSOR ?	1	\$	315.00
19	FRONT PARKING AID SENSOR SEAL RING ✓	6	\$	17.00
20	FRONT BUMPER GUIDE SECTION - RH ?	1	\$	56.00
SUB TOTAL SPARE PARTS			\$	10,034.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 6608 P.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER TOP COVER <i>cm</i>	1	\$ 158.00	
22	"OIL STANDARD" STICKER <i>m</i>	1	\$ 25.00	
23	"CAUTION" STICKER <i>m</i>	1	\$ 25.00	
24	FRONT FOAM FILLER PIECE <i>cm</i>	1	\$ 283.00	
25	FRONT REINFORCEMENT BEAM ?	1	\$ 1,232.00	
26	OUTSIDE TEMP SENSOR BRACKET ?	1	\$ 28.00	
27	FRONT REINFORCEMENT BEAM SUPPORT - LH / RH ?	2	\$ 77.00	
28	FRONT BUMPER BRACKET - RH ?	1	\$ 68.00	
29	HEADLIGHT MOUNTING - LH / RH <i>X</i>	2	\$ 294.00	
30	LED HEADLIGHT - RH <i>cm</i>	1	\$ 10,397.00	
31	LED HEADLIGHT SPACER - RH ?	2	\$ 100.00	
32	LIFT CYLINDER - RH ?	1	\$ 238.00	
33	LIFT CYLINDER HOSE - RH ?	1	\$ 233.00	
34	LIFT CYLINDER BRACKET - RH ?	1	\$ 8.00	
35	LOCK CARRIER TOP COVER - RH <i>cm</i>	1	\$ 55.00	
36	FRONT FENDER - LH / RH <i>R</i>	1	\$ 3,708.00	
37	FRONT FENDER ATTACHMENT PARTS - RH <i>m</i>	1	\$ 94.00	
38	FRONT FENDER BRACE - RH FRONT ?	1	\$ 194.00	
39	FRONT FENDER BRACKET - RH UPPER <i>m</i>	1	\$ 55.00	
40	FRONT WHEEL HOUSING LINER - RH <i>cm</i>	1	\$ 332.00	
SUB TOTAL SPARE PARTS			\$ 17,604.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDD 6608 P.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT WHEEL SPOILER - RH ?	1	\$	207.00	
42	FRONT WHEEL SPOILER TRIM - RH ?	1	\$	45.00	
43	BONNET bfr	1	\$	6,276.00	
44	BONNET ATTACHMENT PARTS X	1	\$	262.00	
45	BONNET HINGE - LH / RH bfr	2	\$	210.00	
46	BONNET SHOCK ABSORBER X	1	\$	143.00	
47	BONNET SOUND ABSORBER X	1	\$	398.00	
48	BONNET IMPACT PROTECTION - LH / RH m-	2	\$	46.00	
49	BONNET IMPACT PROTECTION - CENTER m-	1	\$	56.00	
50	BONNET STRIKER - LH / RH ?	2	\$	274.00	
51	FRONT FENDER TOP COVER - RH der	1	\$	41.00	
52	FRONT FENDER TOP SEALING STRIP - RH ?	1	\$	37.00	
53	BONNET LOCK - LH RH ?	2	\$	399.00	
54	BONNET BOWDEN CABLE - CENTER ?	1	\$	71.00	
55	BONNET RELEASE ELEMENT ?	1	\$	73.00	
56	BONNET BOWDEN CABLE - COVER ?	1	\$	12.00	
57	RADIATOR AIR GUIDE - LH / RH ?	2	\$	108.00	
58	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$	84.00	
59	HORN - RH ?	1	\$	162.00	
60	HORN BRACKET - RH ?	1	\$	59.00	
61	INTERCOOLER PRESSURE HOSE - RH ?	1	\$	375.00	
62	WINDSCREEN WATER DEFLECTOR STRIP - RH cut	1	\$	74.00	
63	FRONT NO PLATE bfr	S/N	\$	60.00	
64	SUNDRIES ?		\$	800.00	
TOTAL SPARE PARTS			:	\$	20,306.00
TOTAL LABOUR CHARGES			:	\$	15,552.00
GRAND TOTAL			:	\$	35,858.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasul - 4p 90010068

: 28/08/24

: 8 days

: EXCESS-TBA

: Repair

: Res 64 paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ~~after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	361J
Vehicle Details	
Vehicle No.:	SDD6608P
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Aug 2024
Vehicle Make:	AUDI
Vehicle Model:	A6 DESIGN 2.0 TFSI (140 KW)
Primary Colour:	Blue
Manufacturing Year:	2022
Engine No.:	DKY016762
Chassis No.:	WAUZZZF23NN031079
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$42,737.00
Original Registration Date:	11 Nov 2022
First Registration Date:	11 Nov 2022
Transfer Count:	0
Actual ARF Paid:	\$51,832.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Nov 2032
PARF Rebate Amount:	\$38,874.00
Intended COE Rebate Details	
COE Expiry Date:	10 Nov 2032
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$115,388.00
COE Rebate Amount:	\$94,616.00
Total Rebate Amount:	\$133,490.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 29 Aug 2024

OK



Audi A6 Mild Hybrid 2.0A TFSI S-tronic Design

\$193,800 Instalment \$1,625/mth

PREMIUM AD

Shortlist

Loan Calculator



Overview Financial Photo Research

Depreciation	\$22,220 / year
Reg. Date	28-Mar-2022 (7yrs 6mths 27days COE left)
Manufactured	2021
Mileage	58,000 km (23.9k / year)
Transmission	Auto
Engine Cap	1,984 cc
Road Tax	\$1,194 / year
Power	140.0 kW (187 bhp) View specs of the Audi A6
Curb Weight	1,680 kg
Fuel Type	Petrol-Electric
COE	\$98,890
OMV	\$41,908