

Date: 26/08/2024
Vehicle No: SNM3435A
Model: TOYOTA PRIUS C 1.5 HYBRID
Chassis: JTDKD3B3701597227-2017
Reg.Year: 2017

Not Authorized
L1 Imp & 2 Roof

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SNP9346T
Date of Accident: 23/08/2024
Estimator: TING AN
Surveyor:

Recovery After Rain

4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		R \$900.00 X
2	REAR TAILGATE "TOYOTA" EMBLEM	1		na \$80.00 X
3	REAR TAILGATE "PRIUS C" EMBLEM	1		na \$75.00 X
4	REAR TAILGATE "HYBRID" EMBLEM	1		na \$80.00 X
5	REAR TAILGATE WEATHERSTRIP	1		R \$285.80 X
6	REAR TAIL LAMP RH	1		M/LM \$530.20 X
7	REAR TAIL LAMP BRACKET RH	1		CM \$75.60 X
8	REAR BUMPER	1		R \$848.70 X
9	REAR BUMPER REINFORCEMENT	1		B \$590.60 X
10	REAR BUMPER SIDE BRACKET RH	1		DIT \$85.40 X
11	REAR END PANEL	1		B \$556.80 X
12	REAR END PANEL UPPER COVER	1		R \$115.20 X
13	REAR FENDER RH	1		REPAIR
SUB TOTAL				\$4,223.30
LESS 25%				-\$1,055.83
PARTS TOTAL				\$3,167.48

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		na \$80.00 X
2	REAR BUMPER CLIPS	1		MC \$50.00 X
3	REAR BUMPER REVERSE SENSOR	1		nd \$300.00 X
4	REAR END PANEL JOINT SEALANT	1		na \$100.00 X
5	REAR END PANEL UPPER COVER CLIPS	1		na \$40.00 X
S/N TOTAL				\$140.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date: 26/08/2024
Vehicle No: SNM3435A
Model: TOYOTA PRIUS C 1.5 HYBRID
Chassis: JTDKD3B3701597227-2017
Reg.Year: 2017

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SNP9346T
Date of Accident: 23/08/2024
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$1,000.00	450/
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR FENDER RH & ETC.	\$1,000.00	800/
LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	na X
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETEC.	\$150.00	na X
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00	50/
TO DAIGNOSIS FAULT CODE & ETC.	\$200.00	na X
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$120.00	15/

LABOUR TOTAL \$2,710.00

TOTAL \$6,017.48

TING AN