



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No.				
			0				
			Document Date				
			26/08/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
NHP1707126465	1NZ8546406	60	Ng Mei Yen	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SHB5969S ACC DATE:26/08/24 TOW IN:26/08/24 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00
2	B	BP-LAB2 CHECK WIRING SYSTEM				198.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
4	L	BP-LPO SUPPLY FRONT REGN PLATE (PO#)				80.00
5	B	BP-MECH2 R/I FRONT UNDERCARRIAGE				1584.00
6	B	BP-MECH2 R/I AIRCON CONDENSER				792.00
7	B	BP-MECH2 R/I DASHBOARD				1584.00
8	B	BP-MECH2 R/I FRONT SEAT BELT RIGHT & LEFT				792.00
9	B	BP-LAB2 REMOVE AND TRANSFER FRONT & REAR RIGHT D OORCOMPARTMENT				1584.00
10	B	BP-LAB2 REMOVE INTERIOR UPHOLSTRY TO FAC REPAIR				792.00
11	B	BP-MECH2 CONDUCT WHEEL ALIGHTMENT				198.00
12	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				8712.00
13	B	BP-RES2 RESPRAY ACC AFF AREA				7872.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 26/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
NHP1707126465	1NZ8546406	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	S	BP-SUBLET SUPPLY FRONT RIGHT & LEFT TYRE 2 PCS				500.00
15	B	BP-MECH2 R/I FRONT RIGHT & LEFH TYRE				198.00
16	1	U52119-52891 C0 COVER, FR BUMPER	1.00	0.00		
17	2	U53395-52080 SEAL, HOOD TO FR END	1.00	32.10		32.10
18	3	U52143-52220 BRACKET, FR BUMPER	1.00	66.80		66.80
19	4	U52144-52230 BRACKET, FR BUMPER	1.00	66.80		66.80
20	5	U52611-52210 ABSORBER, FR BUMPER	1.00	110.20		110.20
21	6	U52131-52250 REINFORCEMENT, FR	1.00	552.30		552.30
22	7	K52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
23	8	U81481-52580 COVER, FOG LAMP, RH	1.00	184.00		184.00
24	9	U81482-52490 COVER, FOG LAMP, LH	1.00	184.00		184.00
25	0	U52618-52100 ABSORBER, FR BUMPER,	1.00	196.70		196.70
26	1	U51441-52290 COVER, ENGINE UNDER,	1.00	179.60		179.60
27	2	U51442-52170 COVER, ENGINE UNDER,	1.00	257.50		257.50
28	3	U53101-52460 GRILLE SUB-ASSY,	1.00	1215.20		1215.20
29	4	U52521-52050 RETAINER, FR BUMPER,	1.00	122.10		122.10
30	5	U53301-52390 HOOD SUB-ASSY	1.00	940.70		940.70
31	6	U53811-52480 PANEL, FR FENDER, RH	1.00	883.80		883.80
32	7	U53812-52480 PANEL, FR FENDER, LH	1.00	883.80		883.80
33	8	U53827-52170 PROTECTOR, FR FENDER	1.00	119.20		119.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 26/08/2024	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
NHP1707126465	1NZ8546406	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	9	U53828-52180 PROTECTOR, FR FENDER	1.00	119.20		119.20
35	0	U53875-52310 LINER, FR FENDER, RH	1.00	262.80		262.80
36	1	U53876-52330 LINER, FR FENDER, LH	1.00	262.80		262.80
37	2	U53510-52610 LOCK ASSY, HOOD	1.00	129.90		129.90
38	3	U53410-52421 HINGE ASSY, HOOD, RH	1.00	92.50		92.50
39	4	T53420-52431 HINGE ASSY, HOOD, LH	1.00	92.50		92.50
40	5	U53210-52918 SUPPORT ASSY,	1.00	1571.40		1571.40
41	6	U53202-52260 SUPPORT SUB-ASSY,	1.00	109.40		109.40
42	7	U53203-52250 SUPPORT SUB-ASSY,	1.00	109.40		109.40
43	8	U53208-52904 SUPPORT S/A, HOOD	1.00	183.40		183.40
44	9	U53285-52510 SEAL, RADIATOR SIDE	1.00	63.40		63.40
45	0	U53287-52260 EXTENSION, RADIATOR	1.00	67.30		67.30
46	1	U53286-52430 SEAL, RADIATOR SIDE	1.00	55.30		55.30
47	2	U53288-52260 EXTENSION, RADIATOR	1.00	56.60		56.60
48	3	U53289-52100 COVER, RADIATOR	1.00	178.90		178.90
49	4	U53701-52250 APRON SUB-ASSY, FR	1.00	909.20		909.20
50	5	U53702-52250 APRON SUB-ASSY, FR	1.00	909.20		909.20
51	6	U57016-52090 REINFORCEMENT	1.00	719.70		719.70
52	7	U57025-52010 MEMBER SUB-ASSY, FR	1.00	358.10		358.10
53	8	U57113-52010 EXTENSION, FR SIDE	1.00	87.10		87.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No.				
			0				
			Document Date				
			26/08/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
NHP1707126465	1NZ8546406	60	Ng Mei Yen	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
54	9	U57197-52030 BOX, TORQUE, FR RH	1.00	253.70		253.70
55	0	U57017-52100 REINFORCEMENT	1.00	638.70		638.70
56	1	U57026-52010 MEMBER SUB-ASSY, FR	1.00	358.10		358.10
57	2	U57114-52010 EXTENSION, FR SIDE	1.00	88.70		88.70
58	3	U57198-52030 BOX, TORQUE, FR LH	1.00	253.70		253.70
59	4	U67001-52560 PANEL SUB-ASSY, FR	1.00	1823.50		1823.50
60	5	U67861-52310 WEATHERSTRIP, FR	1.00	320.90		320.90
61	6	U67923-52230 CUSHION, FR DOOR	1.00	92.50		92.50
62	7	U67003-52580 PANEL SUB-ASSY, RR	1.00	1988.60		1988.60
63	8	U61611-52490 PANEL, QUARTER,	1.00	1006.20		1006.20
64	9	U75075-52050 MOULDING SUB-ASSY,	1.00	155.10		155.10
65	0	U52159-52770 C0 COVER, RR BUMPER	1.00	0.00		
66	1	U52591-52360 SEAL, RR BUMPER	1.00	84.90		84.90
67	2	U52575-52200 RETAINER, RR BUMPER	1.00	107.50		107.50
68	3	U52155-52131 SUPPORT, RR BUMPER	1.00	139.10		139.10
69	4	U52131-52170 REINFORCEMENT, FR	1.00	662.40		662.40
70	5	K52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
71	6	U81130-52K20 UNIT ASSY, HEADLAMP,	1.00	1551.30		1551.30
72	7	U81170-52K20 UNIT ASSY, HEADLAMP,	1.00	1551.30		1551.30
73	8	U16400-21350 RADIATOR ASSY	1.00	3571.20		3571.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	Less
		Others	Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 26/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
NHP1707126465		1NZ8546406	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
74	9	U16361-28360 FAN			1.00	391.70		391.70
75	0	U16361-21130 FAN			1.00	303.30		303.30
76	1	U16711-21180 SHROUD, FAN			1.00	469.50		469.50
77	2	U17700-21200 CLEANER ASSY, AIR			1.00	901.70		901.70
78	3	U17881-21130 HOSE, AIR CLEANER			1.00	120.30		120.30
79	4	U17751-21220 INLET, AIR CLEANER			1.00	79.10		79.10
80	5	U88460-52190 CONDENSER ASSY			1.00	1886.70		1886.70
81	6	UG9010-52010 RADIATOR ASSY			1.00	1140.40		1140.40
82	7	U85315-52420 JAR, WASHER, A			1.00	200.80		200.80
83	8	U48510-52K41 ABSORBER ASSY,			1.00	649.00		649.00
84	9	U48520-52741 ABSORBER ASSY,			1.00	649.00		649.00
85	0	U48820-52030 LINK ASSY, FR			1.00	296.20		296.20
86	1	U48820-52030 LINK ASSY, FR			1.00	296.20		296.20
87	2	U48068-59155 ARM SUB-ASSY,			1.00	1785.70		1785.70
88	3	U48069-59145 ARM SUB-ASSY,			1.00	1785.70		1785.70
89	4	U43211-52050 KNUCKLE, STEERING,			1.00	832.30		832.30
90	5	U43212-52050 KNUCKLE, STEERING,			1.00	832.30		832.30
91	6	U42611-52B00 WHEEL, DISC			1.00	547.30		547.30
92	7	U42602-52560 CAP SUB-ASSY, WHEEL			1.00	294.40		294.40
93	8	U86570-52040 SPEAKER ASSY,			1.00	301.50		301.50
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 26/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
NHP1707126465	1NZ8546406	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
94	9	U86520-68010 HORN ASSY, LOW	1.00	186.60		186.60
95	0	U55302-52200 C0 PANEL SUB-ASSY,	1.00	1299.50		1299.50
96	1	U73960-52240 AIR BAG ASSY, INSTR	1.00	5419.30		5419.30
97	2	U45130-52810 C0 PAD ASSY, STEERING	1.00	4008.70		4008.70
98	3	U84307-47060 CABLE SUB-ASSY,	1.00	1485.10		1485.10
99	4	U89257-30060 COMPUTER, COOLING	1.00	981.30		981.30
100	5	U89173-59305 SENSOR, AIR BAG, FR	1.00	396.90		396.90
101	6	U89173-59305 SENSOR, AIR BAG, FR	1.00	396.90		396.90
102	7	U89170-52P20 SENSOR ASSY, AIR BAG	1.00	1207.90		1207.90
103	8	U73220-52A20 C1 BELT ASSY, FR SEAT,	1.00	1026.70		1026.70
104	9	U73210-52A10 C1 BELT ASSY, FR SEAT,	1.00	1026.70		1026.70
105	0	U75301-52140 EMBLEM SUB-ASSY,	1.00	93.30		93.30
106	1	U75374-52090 EMBLEM, SIDE PANEL	1.00	63.20		63.20
107	2	U75374-52100 EMBLEM, SIDE PANEL	1.00	63.20		63.20
108	3	T08826-08115 PANEL BONDING AD	1.00	267.20		267.20
109	4	L90269-04051 RIVET	40.00	2.20		88.00
110	5	T90269-06013 RIVET	40.00	2.80		112.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 84,165.90
	Please acknowledge receipt of vehicle	Parts 58,981.90 Labour 24,604.00 Sublet 580.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00% 7,574.93 Less 0.00 Amount Due 91,740.83

Customer Copy