

(08/11/13) Waf

ASS. REC. BY:

REF: CS/SMR24080452/R₂³

2004

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 8154C

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 8154C

Yr Regn:

2018 JunType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA SIENNA Hybrid 1.5X c.c 1496

Colour

BLACK

A/C:

Insured / Std / NI / NA

Sp. Reading

382354

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MHP 1707126465Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/08/24

D.O.I.

28/08/24

Survey held at

PANDAN CDes. of Damages Frt Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Lim R 39K

Rasul finalised final fig \$39000, 18 days (Red \$51095.50, 57%)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) 23/10 Typist

Date/Time, File Return to?

2)

Days Of Repair: 18Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$

) : Interview (\$

☐ : Tech. Invs (\$

) : Weekend (\$

☐ : Weekend (\$

) : Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$) 39000

Reg No. : 196700086Z
 Reg No. : MR-8500000-9
 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No.				
			0				
			Document Date				
			26/08/2024				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
NHP1707126465	1NZ8546406	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SHB5969S ACC DATE:26/08/24 TOW IN:26/08/24 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB2 CHECK WIRING SYSTEM				198.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
4	L	BP-LPO SUPPLY FRONT REGN PLATE (PO#				80.00
5	B	BP-MECH2 R/I FRONT UNDERCARRIAGE				1584.00
6	B	BP-MECH2 R/I AIRCON CONDENSER				792.00
7	B	BP-MECH2 R/I DASHBOARD				1584.00
8	B	BP-MECH2 R/I FRONT SEAT BELT RIGHT & LEFT				792.00
9	B	BP-LAB2 REMOVE AND TRANSFER FRONT & REAR RIGHT D OORCOMPARTMENT				792.00
10	B	BP-LAB2 REMOVE INTERIOR UPHOLSTRY TO FAC REPAIR				198.00
11	B	BP-MECH2 CONDUCT WHEEL ALIGHTMENT				8712.00
12	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				5904 7872.00
13	B	BP-RES2 RESPRAY ACC AFF AREA				

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



shcape

Reg No. : 196700086Z

ST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 26/08/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
NHP1707126465		1NZ8546406	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
14	S	BP-SUBLET SUPPLY FRONT RIGHT & LEFT TYRE ¹ / ₂ PCS				?	500.00
15	B	BP-MECH2 R/I FRONT RIGHT & LEFH TYRE				/	198.00
16	1	U52119-52891 C0 COVER, FR BUMPER ^{turn} / ₁	1.00	0.00			
17	2	U53395-52080 SEAL, HOOD TO FR END ^{de} / ₁	1.00	32.10			32.10
18	3	U52143-52220 BRACKET, FR BUMPER	1.00	66.80			66.80
19	4	U52144-52230 BRACKET, FR BUMPER	1.00	66.80			66.80
20	5	U52611-52210 ABSORBER, FR BUMPER ^{cm} / ₁	1.00	110.20			110.20
21	6	U52131-52250 REINFORCEMENT, FR st / ₁	1.00	552.30			552.30
22	7	K52161-0K040 PIECE, RR BUMPER ^{ne} / ₁	10.00	5.80			58.00
23	8	U81481-52580 COVER, FOG LAMP, RH ?	1.00	184.00			184.00
24	9	U81482-52490 COVER, FOG LAMP, LH ^x	1.00	184.00			184.00
25	0	U52618-52100 ABSORBER, FR BUMPER	1.00	196.70			196.70
26	1	U51441-52290 COVER, ENGINE UNDER, ^{de} / ₁	1.00	179.60			179.60
27	2	U51442-52170 COVER, ENGINE UNDER, ^{de} / ₁	1.00	257.50			257.50
28	3	U53101-52460 GRILLE SUB-ASSY, ^{cm} / ₁	1.00	1215.20			1215.20
29	4	U52521-52050 RETAINER, FR BUMPER, ^{cm} / ₁	1.00	122.10			122.10
30	5	U53301-52390 HOOD SUB-ASSY st / ₁	1.00	940.70			940.70
31	6	U53811-52480 PANEL, FR FENDER, RH st / ₁	1.00	883.80			883.80
32	7	U53812-52480 PANEL, FR FENDER, LH ^{rgu} / ₁	1.00	883.80			883.80
33	8	U53827-52170 PROTECTOR, FR FENDER	1.00	119.20			119.20
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Reg No. : 196700086Z

T Reg No. : MR-8500000-9

2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188**ESTIMATE**

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 26/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
NHP1707126465		1NZ8546406	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
34	9	U53828-52180 PROTECTOR, FR FENDER X			1.00	119.20		119.20
35	0	U53875-52310 LINER, FR FENDER, RH cut			1.00	262.80		262.80
36	1	U53876-52330 LINER, FR FENDER, LH X			1.00	262.80		262.80
37	2	U53510-52610 LOCK ASSY, HOOD bt			1.00	129.90		129.90
38	3	U53410-52421 HINGE ASSY, HOOD, RH bt			1.00	92.50		92.50
39	4	T53420-52431 HINGE ASSY, HOOD, LH bt			1.00	92.50		92.50
40	5	U53210-52918 SUPPORT ASSY, bt			1.00	1571.40		1571.40
41	6	U53202-52260 SUPPORT SUB-ASSY, 7.			1.00	109.40		109.40
42	7	U53203-52250 SUPPORT SUB-ASSY, X			1.00	109.40		109.40
43	8	U53208-52904 SUPPORT S/A, HOOD 7.			1.00	183.40		183.40
44	9	U53285-52510 SEAL, RADIATOR SIDE 7.			1.00	63.40		63.40
45	0	U53287-52260 EXTENSION, RADIATOR 7.			1.00	67.30		67.30
46	1	U53286-52430 SEAL, RADIATOR SIDE 7.			1.00	55.30		55.30
47	2	U53288-52260 EXTENSION, RADIATOR 7.			1.00	56.60		56.60
48	3	U53289-52100 COVER, RADIATOR 7.			1.00	178.90		178.90
49	4	U53701-52250 APRON SUB-ASSY, FR bt			1.00	909.20		909.20
50	5	U53702-52250 APRON SUB-ASSY, FR X			1.00	909.20		909.20
51	6	U57016-52090 REINFORCEMENT bt			1.00	719.70		719.70
52	7	U57025-52010 MEMBER SUB-ASSY, FR bt			1.00	358.10		358.10
53	8	U57113-52010 EXTENSION, FR SIDE 7.			1.00	87.10		87.10
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due	



scape

Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd		
			Document No. 0		3 Media Close #01-03/06 Singapore 138498		
			Document Date 26/08/2024		Work: 65703925		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
NHP1707126465		1NZ8546406	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
54	9	U57197-52030 BOX, TORQUE, FR RH ?	1.00	253.70		253.70	
55	0	U57017-52100 REINFORCEMENT ?	1.00	638.70		638.70	
56	1	U57026-52010 MEMBER SUB-ASSY, FR ?	1.00	358.10		358.10	
57	2	U57114-52010 EXTENSION, FR SIDE ?	1.00	88.70		88.70	
58	3	U57198-52030 BOX, TORQUE, FR LH ?	1.00	253.70		253.70	
59	4	U67001-52560 PANEL SUB-ASSY, FR 5t/	1.00	1823.50		1823.50	
60	5	U67861-52310 WEATHERSTRIP, FR 7	1.00	320.90		320.90	
61	6	U67923-52230 CUSHION, FR DOOR 3	1.00	92.50		92.50	
62	7	U67003-52580 PANEL SUB-ASSY, RR 5t/	1.00	1988.60		1988.60	
63	8	U61611-52490 PANEL, QUARTER, 5t/	1.00	1006.20		1006.20	
64	9	U75075-52050 MOULDING SUB-ASSY, ?	1.00	155.10		155.10	
65	0	U52159-52770 C0 COVER, RR BUMPER X	1.00	0.00			
66	1	U52591-52360 SEAL, RR BUMPER X	1.00	84.90		84.90	
67	2	U52575-52200 RETAINER, RR BUMPER X	1.00	107.50		107.50	
68	3	U52155-52131 SUPPORT, RR BUMPER X	1.00	139.10		139.10	
69	4	U52131-52170 REINFORCEMENT, FR 5t/	1.00	662.40		662.40	
70	5	K52161-0K040 PIECE, RR BUMPER X	10.00	5.80		58.00	
71	6	U81130-52K20 UNIT ASSY, HEADLAMP, can -	1.00	1551.30		1551.30	
72	7	U81170-52K20 UNIT ASSY, HEADLAMP, can - photo	1.00	1551.30		1551.30	
73	8	U16400-21350 RADIATOR ASSY ?	1.00	3571.20		3571.20	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due



anchape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 26/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
NHP1707126465		1NZ8546406	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
74	9	U16361-28360 FAN ?			1.00	391.70		391.70
75	0	U16361-21130 FAN ?			1.00	303.30		303.30
76	1	U16711-21180 SHROUD, FAN ?			1.00	469.50		469.50
77	2	U17700-21200 CLEANER ASSY, AIR ?			1.00	901.70		901.70
78	3	U17881-21130 HOSE, AIR CLEANER ?			1.00	120.30		120.30
79	4	U17751-21220 INLET, AIR CLEANER ?			1.00	79.10		79.10
80	5	U88460-52190 CONDENSER ASSY ?			1.00	1886.70		1886.70
81	6	UG9010-52010 RADIATOR ASSY ?			1.00	1140.40		1140.40
82	7	U85315-52420 JAR, WASHER, A ?			1.00	200.80		200.80
83	8	U48510-52K41 ABSORBER ASSY, ?			1.00	649.00		649.00
84	9	U48520-52741 ABSORBER ASSY, ?			1.00	649.00		649.00
85	0	U48820-52030 LINK ASSY, FR ?			1.00	296.20		296.20
86	1	U48820-52030 LINK ASSY, FR ?			1.00	296.20		296.20
87	2	U48068-59155 ARM SUB-ASSY, ?			1.00	1785.70		1785.70
88	3	U48069-59145 ARM SUB-ASSY, ?			1.00	1785.70		1785.70
89	4	U43211-52050 KNUCKLE, STEERING, ?			1.00	832.30		832.30
90	5	U43212-52050 KNUCKLE, STEERING, ?			1.00	832.30		832.30
91	6	U42611-52B00 WHEEL, DISC ?			1.00	547.30		547.30
92	7	U42602-52560 CAP SUB-ASSY, WHEEL ?			1.00	294.40		294.40
93	8	U86570-52040 SPEAKER ASSY, ?			1.00	301.50		301.50
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due	



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
				Document No. 0					
				Document Date 26/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	NHP170	CAT A	20/06/2018	SMA8154C	0	32513	75/DS/SMA8154C		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
NHP1707126465		1NZ8546406	60	Ng Mei Yen	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
94	9	U86520-68010 HORN ASSY, LOW				1.00	186.60		186.60
95	0	U55302-52200 C0 PANEL SUB-ASSY, -				1.00	1299.50		1299.50
96	1	U73960-52240 AIR BAG ASSY, INSTR				1.00	5419.30		5419.30
97	2	U45130-52810 C0 PAD ASSY, STEERING				1.00	4008.70		4008.70
98	3	U84307-47060 CABLE SUB-ASSY, ?				1.00	1485.10		1485.10
99	4	U89257-30060 COMPUTER, COOLING				1.00	981.30		981.30
100	5	U89173-59305 SENSOR, AIR BAG, FR				1.00	396.90		396.90
101	6	U89173-59305 SENSOR, AIR BAG, FR				1.00	396.90		396.90
102	7	U89170-52P20 SENSOR ASSY, AIR BAG				1.00	1207.90		1207.90
103	8	U73220-52A20 C1 BELT ASSY, FR SEAT, ACT				1.00	1026.70		1026.70
104	9	U73210-52A10 C1 BELT ASSY, FR SEAT, ACT				1.00	1026.70		1026.70
105	0	U75301-52140 EMBLEM SUB-ASSY, ACT				1.00	93.30		93.30
106	1	U75374-52090 EMBLEM, SIDE PANEL				1.00	63.20		63.20
107	2	U75374-52100 EMBLEM, SIDE PANEL				1.00	63.20		63.20
108	3	T08826-08115 PANEL BONDING AD				1.00	267.20		267.20
109	4	L90269-04051 RIVET				40.00	2.20		88.00
110	5	T90269-06013 RIVET				40.00	2.80		112.00
For & on behalf of LKK Auto Consultants hence notify Customer's Signature Borneo Motors (Singapore) Pte Ltd • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer						Charge Summary Parts 58,981.90 Labour 24,604.00 Sublet 580.00 Lubrication/Fluid 0.00 Others 0.00		Total 84,165.90 GST 9.00% 7,574.93 Less 0.00 Amount Due 91,740.83	

Customer Copy

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SMA8154C
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	1NZ8546406
Chassis No.:	NHP1707126465
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$22,660.00
Original Registration Date:	20 Jun 2018
First Registration Date:	20 Jun 2018
Transfer Count:	1
Actual ARF Paid:	\$13,724.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2028
PARF Rebate Amount:	\$8,920.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$14,048.00
Total Rebate Amount:	\$22,968.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 29 Aug 2024

OK