



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 ATTN: HUEY NI			Ref: CS/LPC24080472/Eqh3e2(N) Date: 13/01/2025 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	XE 2674G
	Policy No.	Z23VC06115009	Coverage (\$)	0.00
	Claim No.	23/24/24/VC06/029743	Excess (\$)	0.00
	Assign From	HUEY NI	Assign Date	27/08/2024
2. Vehicle Particulars & Condition				
	Make & Model	SCANIA P360CB6X4MHZ	c.c	12742
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	YS2P6X40005444447	Colour	MULTI COLOUR
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	ARISUN	5 mm
	L/H Front Tyre	295/80 R22.5	ARISUN	5 mm
	R/H Rear Tyre	295/80 R22.5 (D)	ARISUN	5/5 mm
	L/H Rear Tyre	295/80 R22.5 (D)	ARISUN	5/5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/08/2024	Inspection Date	28/08/2024
	Survey held at	38 DEFU LANE 9		
	Repairer	WAH HONG MOTORS & CREDIT PTE LTD		
5a. Remarks				
	A) THE MARKET VALUE IS S\$47,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	