

HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE

50, Bukit Batok Street 23,
#02-02, Midview Building, Singapore 659578
Tel: 68966619 Fax: 62678616
Email: huachinmotors2@gmail.com

BIKE NO: FBE5816E YAMAHA YZF-R15

S/N	DESCRIPTION/ MATERAIL	Quotation
1	RIM	\$ 345.00
2	HEADLIGHT	\$ 450.00
3	HEADLIGHT BRACKET	\$ 95.00
4	TOP FEARING	\$ 250.00
5	LEVER	\$ 30.00
6	FRONT MUDGUARD	\$ 75.00
7	HANDLE BAR	\$ 180.00
8	DISC	\$ 125.00
9	FORK	\$ 350.00
10	SPEEDOMETER	\$ 350.00
11	UNDER BRACKET	\$ 280.00
12	SIGNAL LIGHT	\$ 30.00
13	THROTTLE CABLE	\$ 80.00
14	CLUCTH CABLE	\$ 30.00
15	AIR INTAKE L&R	\$ 90.00
16	SIDE COWLING L&R	\$ 360.00
17	FOOTREST	\$ 90.00
18	STERING CONE	\$ 120.00
19	RIM SHAFT	\$ 45.00
20	WIND SCREEN	\$ 150.00
21	MIRROR	\$ 80.00
22	EXHAUST PIPE MUFFLER	\$ 650.00
	TOTAL	\$ 4,255.00
	(LESS 10% DISCOUNT)	-\$ 425.50
		\$ 3,829.50
	PLUSS 7% GST	\$ 344.66
		\$ 4,174.16
	Add special nett items from above	
23	TOWING FEE	\$ 60.00
24	NO. PLATE	\$ 25.00
25	ALIGN BODY	\$ 200.00
26	LABOUR CHARGES	\$ 400.00
	Lump sum repair adjustment	\$ 4,600.00