



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909 ATTN: JOEY TAY			Ref: CS/UOI24080474/Rqp3e2(N) Date: 23/01/2025 Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SGN 2727S	Veh. Inspected	FBE 5816E
	Policy No.		Coverage (\$)	0.00
	Claim No.	M11D00052409	Excess (\$)	0.00
	Assign From	JOEY TAY	Assign Date	27/08/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA YZF-R51	c.c	150
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	ME120P01192020602	Colour	BLUE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	90/80-17	PIRELLI	3 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	120/70-17	PIRELLI	3 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	17/08/2024	Inspection Date	28/08/2024
	Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	