

SHB4168T

COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHB4168T

DATE 27.08.2024

MAKE REG. 31.07.2024

MVA CHIANG/LONPAC

MODEL KONA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR PANEL RH / DD			\$1,789.00 /
1	FRONT DOOR GARNISH RH / RT			\$400.00 /
1	FRONT DOOR HINGE RH ? x nn			\$46.00
1	FRONT FENDER GRANISH RH / RT			\$663.00 /
1	MOULDING ASSY- SIDE SILL RH x nn			\$340.00
1	FRONT FENDER PANEL RH x R			\$928.00
	<b>SUB TOTAL</b>		2852	<b>\$4,166.00</b>
	<b>20.00%</b>		-20%	<b>\$833.20</b>
	<b>DISCOUNTED TOTAL</b>		2281.60	<b>\$3,332.80</b>
1	FRONT DOOR COMFORT LOGO STICKER / PK		75	\$75.00
				<b>\$75.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$950.00 380
	Spray Painting Charge			\$700.00 560
	Remove/refix door parts			\$90.00 50
	<b>TOTAL LABOUR</b>		990	<b>\$1,740.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$5,147.80</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Steve (LKK)

28/8/24, 3.00pm

w L

P/P

by RCL by

3 days

P/P - 3346.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_