

FALCON AIR AUTO SERVICES PTE LTD

Tel.No. :

Estimate : ES709485

Date : 26/08/2024

Vehicle Num. : SMR 8227L

Make/Model : HONDA FIT

Chassis/Eng# :

Accident Date : 26/08/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 PC	O/S REAR DOOR	905.00	1,051.00 ✓
2.	1 PC	O/S REAR DOOR TAPE		65.00 ✓
3.	1 PC	O/S REAR DOOR LOCK		341.00 ✓
4.	1 PC	O/S REAR DOOR REGULATOR GEAR	180.90	331.00 ✓
5.	1 PC	O/S REAR DOOR INNER TRIM BOARD	466.50	641.00 ✓
6.	1 PC	O/S REAR QUARTER GLASS		480.00 X
7.	1 PC	O/S REAR FENDER		891.00 ✓
8.	1 PC	O/S REAR FENDER INNER SHIELD		105.00 X
9.	1 PC	O/S ROCKER PANEL		485.00 X
10.	1 PC	REAR BUMPER	566.20	938.00 ✓
11.	1 PC	O/S REAR BUMPER SIDE RETAINER		37.00 X
12.	1 PC	O/S REAR SHOCK ABSORBER		410.00 X
13.	1 PC	O/S REAR WHEEL HUB		413.00 X
14.	1 PC	O/S REAR DOOR REGULATOR MOTOR	290.00	489.00 ✓
15.	1 PC	REAR AXLE		1,453.00 X
List TotalS\$:				8,130.00
20.00% Discount S\$:				1,626.00
				6,504.00
SPECIAL NETT ITEMS :				
1.	1 PC	O/S REAR DOOR INNER TRIM BOARD CLIPS	30	40.00

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

Estimate : ES709485

Date : 26/08/2024
 Vehicle Num. : SMR 8227L
 Make/Model : HONDA FIT
 Chassis/Eng# :
 Accident Date : 26/08/2024
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1 PC	O/S REAR QUARTER GLASS INNER SEAL 11 X		80.00 X
3.	1 PC	O/S REAR QUARTER GLASS SEALANT 11 30		40.00 30
4.	1 PC	O/S REAR FENDER INNER SHIELD CLIPS 11 X		40.00 X
5.	1 PC	O/S REAR FENDER INNER TRIM CLIPS 11 X		40.00 X
6.	1 PC	REAR BUMPER CLIP 11 30		40.00 30
7.	1 PC	REAR BUMPER RIVET 11 X		40.00 X
8.	1 PC	O/S REAR RIM 11 450		780.00 450
9.	1 PC	O/S ROCKER PANEL BODY SEALANT 11 X		80.00 X
Special Nett Total S\$:				1,180.00
LABOUR :				
TO TRANSFER DOOR GLASS				120.00
TO TRANSFER DOOR MECHANISM				120.00 50
TO REMOVE/REFIT TRIMS AND GARNISH TO FACILITATE REPAIR				250.00 60
TO TRANSFER AND BALANCE TYRES				11 50.00 X
TO REPLACE UNDERCARRIAGE				11 450.00 X
TO CONDUCT COMPETERIZE FOUR WHEEL ALIGNMENT				120.00 X
TO RUST PROOF PANELS				250.00 50
TO FIT REVERSE SENSOR ON NEW BUMPER				50.00 20
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD				1,500.00 700
O/S ROCKER PANEL, O/S REAR FENDER, REPLACEMENT OF PARTS				
AND ALIGN THE SAME				
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA				1,500.00 700
Labour Total S\$:				4,410.00
E. & O.E.			Total S\$:	12,094.00

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

p-3665.00
 202
 2932.00
 540
 1580
 5082
 202
 4041