

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internatio	nale Des Experts En	Automobile	
MS	INCOME INSURA	NCE LTD	Ref:	CS/INC24080481/Aqh3	
	75 BRAS BASAH F	=	Date:	14/10/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLN 3541U	Veh. Inspected	XE 5127A	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1292301-002	Excess	\$0.00	
	Assign From	CHARLOTTE CHEW	Assign Date	28/08/2024	
2.		Vehic	le Details		
	Make & Model	ISUZU CYZ52R	C.C	15681	
	Engine No.	6WG1438420	Year of Reg.	05/09/2019	
	Chassis No.	JALCYZ52RK7000027	Colour	BLUE	
	Odometer	62397 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	295/80 R22.5	LING LONG	6	
	L/H Front Tyre	295/80 R22.5	LING LONG	6	
	R/H Rear Tyre	295/80 R22.5	LING LONG	6	
	L/H Rear Tyre	295/80 R22.5	LING LONG	6	
4. Description of Damages					
THE	VEHICLE SUSTAII	NED DAMAGES AT THE FRONT O/S	PORTION.		
DAM	AGES SEE DETAI	LS.			
5.	General Information				
	Accident Date	24/08/2024	Inspection Date	28/08/2024 (12:16)	
	Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.		Remarks			
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair