

TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

TWINCAR LEASING PTE LTD

2 KAKI BUKIT AVE 2 #01-17

KAKI BUKIT AUTOHUB

SINGAPORE 417921

Repair Code: CLM16407

Date in: 26/08/2024

Vehicle No.: SLT3843S

Model: HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng#: RU31261759/LEB5961776

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	FRONT LH SHOCK ABSORBER <i>Best</i>	L	1	\$ 345.00	\$ 345.00
2	FRONT LH LOWER ARM <i>Best</i>	L	1	\$ 345.00	\$ 345.00
3	FRONT LH KNUCKLE ARM <i>Best</i>	L	1	\$ 486.00	\$ 486.00
4	FRONT LH KNUCKLE ARM BEARING <i>Best</i>	L	1	\$ 205.00	\$ 205.00
5	FRONT LH ALARM SIREN <i>5 months</i>	L	1	\$ 198.00	\$ 198.00
6	FRONT LH SMALL FUSE BOX <i>New</i>	L	1	\$ 125.00	\$ 125.00
7	FRONT LH RESONATOR <i>original</i>	L	1	\$ 115.00	\$ 115.00
Sub total 1: before discount:					\$ 1,819.00
Percentage discount 20%:					\$ 363.80
Sub-total 2: after discount:					\$ 1,455.20
8	FRONT LH TYRE <i>New</i>	S	1	\$ 500.00	\$ 500.00
Sub-total 3 :					\$ 500.00
Parts Total:					\$ 1,955.20

Rear LH door pillar weather strip

at

198.00 ✓

Adrian Cj
2/5 30/08/24

1892

1513.60