

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	LIBERTY INSURAN	CE PTE LTD	Ref:	CS/LIP24080495/Uqh3
ONE RAFFLES QU SINGAPORE 0485		IAY #25-01 NORTH TOWER	Date:	04/10/2024
	SINGAL OILE 04030	3	Code:	LIP
1.	Policy Particulars :- THIRD PARTY CLAIM (PHYSICAL REINSPECTION)			REINSPECTION)
	Insured Veh.	SLP 3408L	Veh. Inspected	SNC 375L
	Policy No.	-	Coverage	0
	Claim No.	AVS24/2245	Excess	\$0.00
	Assign From	ANNIE CHONG	Assign Date	28/08/2024
2. Vehicle Details				
	Make & Model	HONDA JAZZ (A)	C.C	1318
	Engine No.	L13B14100556	Year of Reg.	19/03/2019
	Chassis No.	JHMGK3850KS211410	Colour	BLUE
	Odometer	59927 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		<u> </u>	Make	Polonos (mm)
		Size	Make	Balance (mm)
	R/H Front Tyre	Size 205/50R16	YOKOHAMA	5
	R/H Front Tyre L/H Front Tyre			, ,
		205/50R16	YOKOHAMA	5
	L/H Front Tyre	205/50R16 205/50R16	YOKOHAMA YOKOHAMA	5 5
4.	L/H Front Tyre R/H Rear Tyre	205/50R16 205/50R16 205/50R16	YOKOHAMA YOKOHAMA YOKOHAMA	5 5 5
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/50R16 205/50R16 205/50R16 205/50R16	YOKOHAMA YOKOHAMA YOKOHAMA	5 5 5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/50R16 205/50R16 205/50R16 205/50R16 Description of Application Control	YOKOHAMA YOKOHAMA YOKOHAMA	5 5 5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE HAD COM	205/50R16 205/50R16 205/50R16 205/50R16 Description of Application Control	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA of Damages	5 5 5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE HAD COM	205/50R16 205/50R16 205/50R16 205/50R16 Description of Applement of A	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA of Damages	5 5 5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE HAD COM	205/50R16 205/50R16 205/50R16 205/50R16 205/50R16 Description of the property	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA TOKOHAMA TOKOHAMA TOKOHAMA	5 5 5 5 5
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE HAD COM AIR CONDITION SE	205/50R16 205/50R16 205/50R16 205/50R16 205/50R16 Description of the properties of	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA TOKOHAMA	5 5 5 5 5
THE REP 5. 5a. A) T	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE HAD COM AIR CONDITION SE Accident Date Survey held at	205/50R16 205/50R16 205/50R16 205/50R16 205/50R16 Description of the properties of	YOKOHAMA YOKOHAMA YOKOHAMA YOKOHAMA TOKOHAMA TOK	5 5 5 5 5

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days