

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TO	: CHINA TAIPING	DATE	: 29/8/2024
VEHICLE NO	: PD2202K (2024)	<i>Hui Rong</i>	
VEHICLE MODEL	: TOYOTA HIACE COMMUTER		
CHASSIS NO	: JTFSA22P702007230		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT WING MIRROR <i>Replaced</i>	1	\$ 1,305.10	\$ 1,305.10
2	SLIDING DOOR <i>Dented</i>	1	\$ 1,949.40	\$ 1,949.40
3	SLIDING DOOR LOCK <i>new</i>	1	\$ 395.50	\$ 395.50
4	SLIDING DOOR GLASS <i>Shattered</i>	1	\$ 875.60	\$ 875.60
5	SLIDING DOOR RAIL <i>new</i>	1	\$ 485.40	\$ 485.40
6	SLIDING DOOR RAIL COVER <i>Reis</i>	1	\$ 189.30	\$ 189.30
7	REAR BODY PANEL <i>Reis</i>	1	\$ 3,750.40	\$ 3,750.40
8	REAR BODY PANEL GLASS (FRONT) <i>shattered</i>	1	\$ 670.90	\$ 670.90

TOTAL PRICE: \$ 9,621.60
LESS 25% \$ 2,405.40
SUB TOTAL PRICE: \$ 7,216.20

4801
3600.75

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	SLIDING DOOR GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
2	EXCURSION STICKER <i>new</i>	1	\$ 30.00	\$ 30.00
3	REAR BODY PANEL GLASS (FRONT) SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
4	REAR WHEEL RIM COVER <i>at</i>	1	\$ 200.00	\$ 200.00

TOTAL : \$ 350.00

300

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	<i>400</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 800.00	<i>500</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TUFF COAT	\$ 150.00	<i>40</i>	
5	TO REPLACE SLIDING DOOR GLASS	\$ 100.00	<i>40</i>	
6	TO TRANSFER SLIDING DOOR FITTINGS	\$ 150.00	<i>40</i>	
7	TO REMOVE REAR BODY PANEL GLASS	\$ 150.00	<i>80</i>	
8	TO VACCUM SHATTERED GLASSES	\$ 150.00	<i>60</i>	

TOTAL: \$ 2,550.00

1190

ESTIMATE REPORT

TOTAL PARTS COST: \$ 7,566.20
TOTAL LABOUR COST: \$ 2,550.00
TOTAL REPAIR COST: \$ 10,116.20

- Entrusted Consultants hence notify the Repairer of the following:*
- To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5090.75

L/S: HK

OS Days