

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road
Springleaf Tower #16-00
Singapore 079909

Tel: 63896111 Fax: 6221033
Attn: Motor Claim Department \ CHINA
TAIPING

Your Ref No: TP 0824-8214
Claim Type: Third Party
Accident Date: 27 August 2024
TP Veh Reg No: SJQ7662K

Not Allowed
in
Merous
29/8/24
2/5 #12,000
change the up
7 days

Estimate No: EST1511707
Date: 27 Aug 2024
Policy No: MT/00896011/03
Veh Reg No: SLW3127K
Make/Model: MAZDA MAZDA6 SEDAN
2.0 AT EXECUTIVE EU6
Chassis No: JM6GL1071J0134791
Engine No: PE21016607
Reg. Date: 06 Feb 2018

Estimate Repair Cost to Vehicle No: SLW3127K

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 FRONT BUMPER	1,211.00	1 PC	1,211.00	✓
2 FRONT BUMPER SIDE RETAINER - LH/RH	39.00	2 PC	78.00	✓
3 FRONT BUMPER CLIPS	5.50	10 PC	55.00	✓
4 FRONT BUMPER FOAM	98.00	1 PC	98.00	✓
5 FRONT BUMPER REINFORCEMENT	579.00	1 PC	579.00	✓
6 FRONT BUMPER REINFORCEMENT GUIDE GARNISH	128.00	1 PC	128.00	✓
7 FRONT BUMPER SENSOR - RH	195.00	2 PC	390.00	X
8 FRONT BUMPER CENTER LOWER GRILLE	105.00	1 PC	105.00	X
9 FRONT BUMPER TOP GARNISH (SPRAY)	448.00	1 PC	448.00	✓
10 FRONT BUMPER TOP INNER GARNISH (SMALL-BLACK)	78.00	1 PC	78.00	✓
11 FRONT BUMPER TOP INNER GARNISH (BIG-BLACK)	121.00	1 PC	121.00	✓
12 FRONT BUMPER TOP GARNISH RIVET	5.90	7 PC	41.30	✓
13 FRONT BUMPER TOP GARNISH SMALL CLIPS	4.80	7 PC	33.60	✓
14 FRONT BUMPER FOGLAMP - RH	736.00	1 PC	736.00	X
15 FRONT BUMPER FOGLAMP COVER -RH	49.00	1 PC	49.00	X
16 FRONT BUMPER FOGLAMP TOP CHROME - RH	102.00	1 PC	102.00	X
17 FRONT BUMPER SENSOR - LH/RH (INNER)	195.00	2 PC	390.00	X
18 FRONT BUMPER TOP BEAM	139.00	1 PC	139.00	X
19 FRONT GRILLE BASE	145.00	1 PC	145.00	✓
20 FRONT GRILLE LOGO	59.00	1 PC	59.00	✓
21 FRONT GRILLE LOGO BASE	56.00	1 PC	56.00	✓
22 FRONT GRILLE OUTER CHROME - LH/RH	169.00	2 PC	338.00	✓
23 FRONT GRILLE INNER BRACKET - LH/RH	1,050.00	2 PC	2,100.00	g
24 FRONT GRILLE INNER BRACKET WHITE PIN - LH/RH	8.90	2 PC	17.80	X
25 FRONT GRILLE PROTECTOR SHORT (1ST FROM TOP) - RH	54.00	1 PC	54.00	✓
26 FRONT GRILLE PROTECTOR SHORT (2ND FROM TOP) - RH	54.00	1 PC	54.00	✓
27 FRONT GRILLE PROTECTOR SHORT (3RD FROM TOP) - RH	58.00	1 PC	58.00	✓
28 FRONT GRILLE PROTECTOR SHORT (4TH FROM TOP) - RH	58.00	1 PC	58.00	✓
29 FRONT GRILLE PROTECTOR TOP (LONG)	84.00	1 PC	84.00	✓
30 FRONT GRILLE PROTECTOR LOWER (LONG)	84.00	1 PC	84.00	✓
31 HEADLAMP UNIT - LH/RH	4,056.00	2 PC	8,112.00	1 PC
32 HEADLAMP LOWER RETAINER - LH/RH	58.00	2 PC	116.00	X
33 HEADLAMP ADJUSTER (INNER) - LH/RH	56.00	2 PC	112.00	X
34 HEADLAMP ADJUSTER (OUTER) - LH/RH	56.00	2 PC	112.00	X
35 SUPPORT PANEL ASSY	492.00	1 PC	492.00	X
36 REAR BUMPER	1,230.00	1 PC	1,230.00	✓
37 REAR BUMPER SIDE RETAINER - LH/RH	42.00	2 PC	84.00	X
38 REAR BUMPER CLIPS	4.80	10 PC	48.00	✓
39 REAR BUMPER REINFORCEMENT	541.00	1 PC	541.00	✓

9624.71

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

40	REAR BUMPER SENSOR	195.00	4 PC	molten	780.00	2 pgs 390
41	REAR BUMPER SENSOR WIRE	181.00	1 PC	11	181.00	X
42	REAR BUMPER TOW COVER - LH/RH	42.00	2 PC	mis	84.00	✓
43	REAR BUMPER REFLECTOR - LH/RH	54.00	2 PC	11	108.00	X
44	REAR BOOT	1,114.00	1 PC	DD	1,114.00	✓
45	REAR BOOT HINGE - LH/RH	258.00	2 PC	11	516.00	X
46	REAR BOOT WEATHERSTRIP	138.90	2 PC	11	277.80	✓
47	REAR BOOT TOP LOCK	160.00	1 PC	11	160.00	✓
48	REAR BOOT LOWER LOCK STRIKER	50.40	1 PC	11	50.40	X
49	REAR BOOT LAMP - LH/RH	768.00	2 PC	11	1,536.00	X
50	REAR BOOT "MAZDA 6" WORDINGS	71.00	1 PC	11	71.00	✓
51	REAR BOOT MAZDA LOGO	55.00	1 PC	11	55.00	✓
52	REAR BOOT SKYACTIV LOGO	74.00	1 PC	11	74.00	✓
53	REAR BOOT INNER TRIM	172.00	1 PC	11	172.00	X
54	REAR BOOT INNER TRIM CLIPS	4.80	10 PC	11	48.00	X
55	TAILLAMP - LH/RH	1,826.00	2 PC	11	3,652.00	12 C
56	REAR END PANEL	666.70	1 PC	11	666.70	✓
57	REAR END PANEL TOP GARNISH	132.00	1 PC	11	132.00	✓
58	REAR END PANEL TOP GARNISH SMALL COVER	29.00	1 PC	11	29.00	✓
59	REAR SPARE TYRE TOOLBOX FOAM - LH	237.00	1 PC	11	237.00	X
60	REAR SPARE TYRE TOP BOARD	651.00	1 PC	11	651.00	✓
					29,331.60	
					Less 20%	-5,866.38
						23,465.22

Special Net

61	REAR NUMBER PLATE WITH CASING	35.00	1 SET	511	35.00	X
62	FRONT NUMBER PLATE WITH CASING	35.00	1 SET	511	35.00	✓
63	COOLANT	50.00	1 PC	11	50.00	X
64	REAR BUMPER TOP STEP GARNISH	200.00	1 PC	11	200.00	80
						320.00

Labour

65	FRONT - TO KNOCK OUT DENTS ON FRONT 2 FENDER, BONNET, REPLACE SUPPORT PANEL, REMOVE, REPLACE ACCIDENT PORTIONS	800.00	1 PC		800.00	400
66	REAR - TO KNOCK OUT DENTS, CUT/WELD END PANEL, REMOVE, REPLACE ACCIDENT PORTIONS	900.00	1 PC		900.00	700
67	TO RESPRAY PAINT ON FRONT AND REAR ACCIDENT PORTIONS	1,800.00	1 PC		1,800.00	1500
68	TO CHECK WIRING	50.00	1 PC		50.00	30
69	TO REMOVE, REFIT A/C CONDENSER & REFILL GAS	100.00	1 PC	11	100.00	X
70	TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR	150.00	1 PC		150.00	60
71	TO REMOVE, REPLACE FRONT & REAR BUMPER SENSOR	120.00	1 PC		120.00	30
72	TO TRANSFER REAR BOOT	80.00	1 PC		80.00	50
73	TO TUFFKOTE	90.00	1 PC		90.00	60
						4,090.00

FITTINGS: Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

1-1513499
202
12/07/99

115
2830
1502.99

Total 27,875.22
Add GST @ 9% 2,508.77
Total Amount Payable SGD 30,383.99

SINGAPORE DOLLAR THIRTY THOUSAND THREE HUNDRED EIGHTY THREE AND CENTS NINETY NINE ONLY

Acknowledged by Repairer
Signature:
Date:

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE