

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SMV7575S

MAKE & MODEL: BYD ATTO 3

FRONT DOOR LH	22/Bent	2650	\$4,215.70 ✓
FRONT DOOR WEATHERSTRIPE LH	11		\$210.80 X
FRONT DOOR WINDOW GLASS OUTER MOULDING LH	11		\$164.80 X
FRONT DOOR LOWER BLACK GARNISH LH	See		\$368.80 X
FRONT DOOR LOWER SILVER PROTECTOR LH	Cur/Pe	260.00	\$329.10 ✓
FRONT DOOR INNER TRIMBOARD LH	11		\$951.20 X
REAR DOOR LH	22/Bent	2350	\$4,088.90 ✓
REAR DOOR WEATHERSTRIPE LH	11		\$210.80 X
REAR DOOR WINDOW GLASS OUTER MOULDING LH	11		\$164.80 X
REAR DOOR LOWER BLACK GARNISH LH	See		\$368.80 X
REAR DOOR LOWER SILVER PROTECTOR LH	Cur	240.00	\$329.10 ✓
REAR DOOR INNER TRIMBOARD LH	11		\$942.70 X
			<u>\$12,345.50</u>
		Less 10%	<u>\$1,234.55</u>
			\$11,110.95

FRONT DOOR TRIMBOARD CLIPS RH	11	\$100.00 X
REAR DOOR TRIMBOARD CLIPS RH	11	\$100.00 X
		<u>\$200.00</u>

TO CHECK FRONT WIRING	\$80.00 20
TO REMOVE AND REFIT DOOR SIDE MIRROR RH	11 \$150.00 X
TO REMOVE AND TRANSFER FRONT RH DOOR FITTINGS	\$120.00 } 120
TO REMOVE AND TRANSFER REAR RH DOOR FITTINGS	\$120.00 }
TO PROVIDE LABOUR, WORKMANSHIP	\$800.00 200
TO SPRAY PAINT ON AFFECTED PANELS	\$800.00 500
RUST PROOFING	\$100.00 50
	<u>\$2,170.00</u>

Total **\$13,480.95**

Not Authorised
29/8/24
L/S 4600/
3 days
Wk ph. After 14p-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, to be resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5100
102
4950.
890
5840
202
4632.