

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090003/UMA3Q2
Date: 19/09/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_03
Claimant Vehicle No : FBG4591Z Insured Vehicle No : SML6925A
Date of Loss: 19/08/2024 Nature of Claim: TP Claim No: MFL2024D0009590

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBG4591Z
Make & Model: PIAGGIO VESPA LX 150, 151cc CVT Engine No: M682M3004097
Reg. Date: 25/07/2012 (Man. Year: 2012) Chassis No: ZAPM6820000009911
Colour: Green Odometer: 38856 km
Engine Capacity: 151 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110-70-11 Rear Tyre Size: 120/70-10
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 29/08/2024
Date Inspected: 29/08/2024 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Singapore 533758
Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$5,000.00

LTA REIMBURSEMENT VALUE (RV) : \$2,963.00

NETT VALUE : \$2,037.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Reference		
Part Source:		
Parts:	N/A	PIAGGIO VESPA LX 150 151cc CVT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG4591Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >