

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: EDMUND LAW

Date: 09/09/2024

PRELIMINARY ADVICE

Vehicle No	SNG 9810S	Accident Date	29/08/2024
Make	BYD E6 (ME-2)	CLAIM No.	TP / MPC2024D0010226
Assignment Date	02/09/2024	Excess	-
Inspection Date	02/09/2024	Est. Duration of Repair	4

Inspected At: CARSMITH PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	\$	23,991.77
Revised Estimate Amount:	\$	7,260.51
"Check" Items Amount		\$0.00
Total	\$	7,260.51

Total Loss Consideration

Book Value	\$0.00
Market Value	\$95,000.00
COE / PARF Rebate	\$63,491.00
Salvage Value	\$0.00
Margin for Repair	\$31,509.00

Remarks

- [] The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- [] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- [] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.