

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBG1705H
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Not With Claim

WS Ref: TP/AIG

11 Rm 85200h

Claim Type: Third Party

Accident Date: 30/08/2024

Recovery After Rain

TP Veh Reg No: GBA1902L

Estimate No: ES2400750/WS

Date: 09 Sep 2024

Policy No: 5091948538-07

Veh Reg No: GBG1705H

Make/Model: TOYOTA TOYOTA
HIACE DX 3.0 M

Chassis No: KDH2015025199

Engine No: 1KD2676027

Reg. Date: 15/06/2017

4 days

Estimate Repair Cost to Vehicle No :GBG1705H

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER	836.90	1 PC	836.90	✓
2 FRONT BUMPER RH RETAINER	126.10	1 PC	126.10	✓
3 FRONT BUMPER CLIPS	4.50	6 PC	27.00	✓
4 FRONT RH STEP TRAY	224.70	1 PC	224.70	✓
5 FRONT RH WIPER SIDE GARNISH EXTENSION	48.70	1 PC	48.70	✓
6 HEADLAMP RH	3,967.50	1 PC	3,967.50	✓
7 FRONT RH DOOR	2,904.60	1 PC	2,904.60	X
8 FRONT RH DOOR GLASS	746.80	1 PC	746.80	✓
9 FRONT RH DOOR GLASS OUTER MOULDING	128.60	1 PC	128.60	✓
10 FRONT RH SIDE MIRROR	1,507.50	1 PC	1,507.50	✓
11 FRONT RH CORNER PANEL	409.30	1 PC	409.30	X
			10,927.70	
		Less 25%	2,731.93	8,195.78
Special Net				
12 FRONT RH DOOR COMPANY STICKER	20.00	1 PC	20.00	✓
			20.00	20.00
Labour				
13 PANEL BEATING	600.00	1 LA	600.00	450
14 REMOVE AND REFIT FRT RH DOOR GLASS	50.00	1 LA	50.00	X
15 PUTTY AND RESPRAY ON FRT RH CORNER PANEL, FRT RH DOOR AND SIDE MIRROR.	500.00	1 LA	500.00	320
			1,150.00	1,150.00

Total S\$ 9,365.78

Add GST @ 9% 842.92

Total Amount Payable S\$ 10,208.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE