SS. REG. BY: Marcus ASS	IGNMENT
rom: Date:	Veh No: 5173903 CYr Regn: 15/06/16
rom: Date:stimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLD 39032	Make: Yoyas Carry 2.0 c.c 1998
t Workshop m/s Www 2 4 40~	Colour MLe A/C: Insured / Std / NI / NA
of	Sp.Reading 178465 T/Radio: Insured / Std / NI / NA
nsured: SLL SZSSH	Eng/No:
Policy No.	C/No: MRUS3DKS/00/07273
Claims No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Iporder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R: 215/60-216
Remark: The veh had commenced its N/S 0/\$	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	тоуо (уоко) or
Bal, or Market Value: 6 4 W.	Front 6 Rear 6
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. mm L/Bal. mm
Est. Repairs:	D.O.A. 28/08/24 D.O.I. 2/8/2/
Lum Sum: % 3 Val.: Yes or No	Survey held at
020/	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	JT 0/5 Boon &
Date: Person Contacted: L1A & WUG	The U/C Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction Dog 164.	
10/21/	
0/9/24 1/5 \$5.400 inhund Jo.	shio
,	
,	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
Date/Time, File Pass to? : Preli. Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Pass to? : Preli. Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:
Date/Time, File Pass to? : Preli. Report 1) : Final Report	Resurvey No. of Trip: Survey Fee: Transportation: See: Site Insp (\$)S+RS,SI
Date/Time, File Pass to? 1) Date/Time, File Return to? Add F	Resurvey No. of Trip: Survey Fee: Transportation:

Wheelz 4 You

To: Motor Claims Department

Vehicle No: SLD3903L Model: TOYOTA CAMRY Not Authory

1/5 57

1/5 \$ 5700

Date: 02/09/2024

TOYOTA CAMRY Ch M. Att M.

1/565700

	ESTIMATE For SLD3903L TOYOTA CAMRY CW 101	(
QTY	Parts		Amount	
1	RH REAR DOOR > /2ut	\$	1,450.00	
1	RH REAR DOOR TAPE	\$ 60	138.00	
1	RH REAR DOOR WEATHERSTRIP 11X	\$	259.00X	
1	RH REAR DOOR LOCK AT X	\$	651.00X	
1	RH SIDE SKIRT 247/700	\$	590.00	
1	RH REAR FENDER	\$	869.00人	
1	RH REAR FENDER INNER SHIELD AAX	\$	311.00×	
1	REAR BUMPER 201/73/	\$	723.00	
1	RH REAR BUMPER SIDE RETAINER 714 X	\$	143.00 X	
1	RH REAR RIM (40)	\$	1,976.00	
1	RH REAR SHOCK ABSORBER 344 392.00	\$	404.00	
1	RH REAR WHEEL BEARING Maye	\$	633.00	
1	REAR WINSCREEN MOULDING 11X	\$	198.00 ×	
1	RH WING MIRROR CAR/92 / 450.20	\$	1,639.00	
	Parts Sum:	\$	9,984.00	
	Parts Less 25%:	\$	2,496.00	
	Parts Total:	\$	7,488.00	
	Special Nett Items		,	
1	RH REAR DOOR INNER TRIM CLIPS \sim 1 \sim	\$	40.00 义	
1	RH REAR FENDER INNER SHIELD CLIP 11	\$	40.00 🗴	
1	RH SIDE SKIRT CLIP PM	\$	40.00	
1	REAR BUMPER CLIPS	\$	40.00	
1	REAR BUMPER RIVET	\$	40.00 X	
1	REAR WINDSCREEEN INNER SEAL MAX	\$	80.00 🗶	
1	REAR WINDSCREEN SEALANT	\$	40.00 🗶	
	Special Nett Items Total:	\$	320.00	

Labour & Misc Charges

Description	Amount	
TO CHECK REAR PORTION WIRING	\$	50.00 20
TO FIT REVERSE SENSOR ON NEW BUMPER	\$	50.00
TO RESET PDC	\$	1 350.00 X
TO TRANSFER RH REAR DOOR GLASS	\$	حکد 120.00
TO TRASNFER RH REAR DOOR MECHANISM	\$	120.00
TO RE-CALIBRATE RH REAR CENTRAL LOCKING	\$	250.00
TO RE-CALIBRATE RH REAR POWER WINDOW	\$	250.00
TO TRASNFER RH REAR TYRE ON NEW RIM PLUS BALANCING	\$	10.00 X

350.00 /50 \$ TO REPLACE RH REAR UNDERCARRIAGE 120.00 80 \$ TO CONDUCT 4 WHEEL ALIGNMENT \$ 120.00 X TO REMOVE/REFIX REAR WINDSCREEN \$ 250.00 60 TO REMOVE/REFIX INNER TRIM, GARNISHES TO FACILITATE REPAIR \$ 1,200.00 5 80 TO PANEL BEAT AND REPLACEMENT OF PARTS \$ 1,200.00 1000 TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA Labour Charges Total: \$ 4,480.00

Parts Total: \$ 7,488.00
Special Nett Items Total: \$ 320.00
Labour Charges Total: \$ 4,480.00
Total Cost Of Repair: \$ 12,288.00

(Non-Inclusive of GST)

KK Auto Consultants hence noully

the Repairer of the following:

P Te resurvey before/after spray painting

To display damaged part(a), in the meuropy

o Porte prices are subject to confiner from

· Third party survey is on a "Without Prejudior" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comparison

Acknowledged by Repairer

Signature

Date:

FAR EAST TYRES && BATTERIES TRADING BLOCK 9002 TAMPINES STREET 93

#01-32 528836

SINGAPORE

TEL: 67851902 FAX: 67494328

Work Order:

R001553

VIN:

SLD3903L

Date


2.9.24 17:25



Toyota: Camry/Aurion: ASV70 GSV70 AXVA70 (2017.9-2017.12): ASV70 AXVA70 (except Rough Road Suspension): with 205/65R16, 215/55R17 Tire

4-Wheel Total Alignment

Current Measurements







Negative Camber could cause road shock or poor ride quality.


Excessive Toe causes scuffing, shoulder wear and poor fuel economy.

Negative Caster could cause reduced directional stability.

Negative Caster could cause reduced returnability.









- Excessive Camber causes shoulder wear and poor handling.
- Excessive Toe causes scuffing, shoulder wear and poor fuel economy.





This vehicle's Steering Angle Sensor may require calibration using an OEM scan tool after alignment.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: /ehicle Details	937G
/ehicle No.:	SLD3903L
/ehicle to be Exported:	No
ntended Deregistration Date:	02 Sep 2024
/ehicle Make:	TOYOTA
/ehicle Model:	CAMRY 2.0 AUTO
rimary Colour:	White
Nanufacturing Year:	2016
ngine No.:	6ARP178213
Chassis No.:	MR053DK5100107273
laximum Power Output:	123.0 kW (164 bhp)
pen Market Value:	\$28,695.00
Original Registration Date:	15 Jun 2016
irst Registration Date:	15 Jun 2016
ransfer Count:	0
ctual ARF Paid: ntended PARF Rebate Details	\$32,173.00 /6086
ARF Eligibility:	Yes
ARF Eligibility Expiry Date:	14 Jun 2026
ARF Rebate Amount: ntended COE Rebate Details	\$17,695.00
OE Expiry Date:	14 Jun 2026
OE Category:	B - Car above 1600cc or 97kW (130bhp)
OE Period(Years):	10
P Paid:	\$49,156.00
OE Rebate Amount:	\$8,766.00
otal Rebate Amount: lessage	\$26,461.00
ou will not be eligible for any COE rebate from the eriod/s), if you renew your COE.	ne current COE (including unused COE from any lay-up

The information contained herein is correct as at 02 Sep 2024







Login | Sign Up

New

Post an Ad

Used

Electric

Loan

Rent Sell Directory

e-Shop

Insurance

Articles

Fc

Post an Advertisement Sell it yourself! Advertise it at just \$72 until it's SOLD!

Advertiser Login



Carz World Pte Ltd



Sort by Date Posted

2 vehicles TOYOTA CAMRY 2.0 Basic Search Price Any price Depre Any depre Reg Date 2016 to 2016 Eng Cap Any Fuel Any fuel Gear Any Gear Mileage Any Past Owners Any

Category All categories

Scheme All schemes

Ways of Selling

OMV Any

Veh Type All typ

Dealer Any Dealer ✓ Location Any Status Availal

Make & Model

Price

Depreciation

Reg Date

Eng Cap Mileage Veh Type

Toyota Camry 2.0A

\$38,000

\$16,900 /yr

06-Jan-2016

1,998 cc

120,000 km

Luxury

Whatsapp now to view!

Posted: 30-Aug-2024

Toyota Camry 2.0A

\$51,000

\$17,220 /yr

13-Sep-2016

1,998 cc

91.997 km

Luxury

Drop by Carro to view the largest fleet in Singapore with 100% transparency on our vehicle condition, financing available, service add-ons and many more.

Carro

Posted: 18-Jul-2024

Save this search criteria, to get email alerts whenever a match is found.

Make & Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

For old advertisements, view Expired ads

20

Sell Your Car Buy / Rent Cars Aftermarket Articles General Car Reviews New Cars For Sale Post an Ad Workshop Directory About Us Used Cars For Sale Sell by Bidding Aftermarket Products Car Advice Contact Us Cars For Rent Sell by Consignment Car News Careers Car Features Site Map

Re

Follow Sgcarmart.com