



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Claim Details

Case Ref. No. : TP
Date : 23-08-2024
Accident Date : 18-08-2024

Vehicle Details

Make & Model : Opel CROSSLAND X B12XHT AT
Chassis No : W0V7D9ED0J4140780
Registration No : SKT8525P

Third Party Vehicle Details

Registration No : SHB5685K

S/N	Description	Qty	Amount (\$\$)
1	FRONT BUMPER	1.00	\$1,831.00
2	FRONT BUMPER LH OUTER PARKING SENSOR	1.00	\$285.00
3	FRONT BUMPER LOWER PAD	1.00	\$190.00
4	FRONT BUMPER LH SIDE RETAINER	1.00	\$72.00
5	FRONT BUMPER CLIPS	10.00	\$110.00
6	LH SIDE MIRROR ASSY	1.00	\$810.00
			\$3,298.00
Discount: -10%			(\$329.80)
			\$2,968.20
7	TO RESET HEADLAMP SYSTEM	1.00	\$280.00
8	TO REPAIR DAMAGES	1.00	\$380.00
9	TO SPRAY PAINTING	1.00	\$480.00
Subtotal w/o GST:			\$4,108.20

Not withain
1/1hr & 2600h
Penny After Penny
4 days

Issued by Elaine Lee

This is a computer-generated document. No signature is required.

Acknowledged by Repairer

Signature:

Date: