



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 31/08/24
VEHICLE : SMS2654X
MAKE/MODEL : HONDA SHUTTLE
CHASSIS NO : GP7-2002496
MILLAGE : 365200KM
TYRE SIZE :
DOA : 29/08/24

Not Authorized
L1 Pay & 5000/-
Running After Rain
5 days

List items

01 PC	REAR BUMPER	1050.60	Per \$	2,291.40	✓
01 PC	REAR RH BUMPER REFLECTOR GANISH		\$	177.36	X
01 PC	REAR RH BUMPER REFLECTOR		\$	163.20	X
01 PC	REAR BUMPER TOWING COVER		\$	42.84	X
02 PC	REAR BUMPER SIDE RETAINER @ \$121.95		CLSDI \$	243.90	X
01 PC	REAR BUMPER RH INNER SIDE PROTECTOR		\$	65.28	X
01 PC	REAR BUMPER MOULDING		NJP \$	219.60	X
01 PC	REAR BUMPER INNNER BRACKET		\$	60.06	X
01 PC	REAR END PANEL	681.20	\$	854.30	X
01 PC	REAR END PANEL TOP GANISH		\$	236.10	X
01 PC	REAR TAIL GATE WEATERSTRIP	166.50	DIJ/100 \$	299.46	X
01 PC	REAR TAIL GATE	1193.20	BI \$	2,522.22	✓
01 PC	REAR TAIL GATE OUTER GANISH		\$	387.85	X
01 PC	REAR TAIL GATE OUTER CHROME GANISH		CM \$	286.30	✓
01 PC	REAR TAIL GATE EMBLEM 'LOGO'	98.70	CM \$	125.70	✓
01 PC	REAR TAIL GATE EMBLEM 'SHUTTLE'	92.50	CM \$	145.20	✓
01 PC	REAR TAIL GATE EMBLEM 'HYBIRD'	94.30	CM \$	105.60	✓
01 PC	REAR TAIL GATE OUTER HANDLE		\$	165.40	X
02 PC	REAR TAIL GATE NUMBER PLATE LAMP @ \$98.40		\$	196.80	X
01 PC	REAR RH TAIL LAMP	592.30	CM \$	943.05	✓
01 PC	REAR RH TAIL GATE LAMP	580.90	CM \$	891.08	✓
01 PC	REAR TAIL GATE INNER TRIM BOARD	320.60	Bu/100 \$	781.60	✓
01 PC	REAR WIPER MOTOR		\$	732.60	X
02 PC	REAR TAIL GATE ABSORBER @ \$299.46		\$	598.92	X
01 PC	REAR TAIL GATE INNER LOCK		\$	456.85	X
01 PC	REAR TAIL GATE CATCH LOCK		\$	96.30	X
01 PC	REAR TAIL GATE INNER HANDLE		\$	93.35	X
02 PC	REAR TAIL GATE STOPPER @ \$25.00		\$	50.00	X
TOTAL PARTS COST		019C fender inner trim board. RH Rear.	\$ 13,232.32		✓
		mgcm \$488.00			✓

Special Nett Item:

10 PC	DOOR TRIM BOARD CLIP @ \$8.00	MA \$	80.00	✓
02 PC	PARKING SENSOR @ \$250.00	\$	500.00	X
01 PC	REAR PARKING CAMERA	\$	520.00	X
05 PC	REAR BUMPER CLIP @ \$8.00	\$	40.00	✓
01 PC	WINDSCREEN SEALANT	\$	100.00	400.00
		\$	1,240.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	800.00	✓
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$	600.00	
3. TO SUPPLY LABOUR TO DISMANTLE & REFIT REAR WINDSCREEN	\$	300.00	1200
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	100.00	200
5. TO SUPPLY COMPUTER DIANOGTIC		250.00	x
	\$	2,050.00	

TOTAL PARTS
SPECIAL NETT ITEM
TOTAL LABOUR
TOTAL COST OF REPAIR

\$ 13,232.32
\$ 1,240.00
\$ 2,050.00
\$ 16,522.32