

## SINGAPORE CIVIL DEFENCE FORCE

# FIRE REPORT

# 1. GENERAL INFORMATION INCIDENT NO.: /20240821/0038 LOCATION OF FIRE: FIRE REPORTED ON: 21 August 2024 Along the internal driveway 20, Kranji Crescent Singapore 728657 STATION COVERAGE: Woodlands Fire Station

### 2. INCIDENT INFORMATION

FIRE INVOLVED: The front section of an Isuzu tipper truck (XD2119Z) parked along the internal driveway of the industrial building.

METHOD OF EXTINGUISHMENT: By SCDF crew using hose line water jets from fire appliances.

PROBABLE CAUSE OF FIRE: Accidental (Electrical origin from the cabin and / or engine compartment)

DAMAGE OBSERVED\*: As a result of the fire, the front section of the Isuzu tipper truck (XD2119Z), comprising the cabin and engine compartment, was damaged. Other parts of the tipper truck sustained heat, smoke and water damage.

The internal driveway and facade of the industrial building as well as a nearby Scania tipper truck (XE2674G) sustained varying degrees of heat, smoke and water damage.

### 3. FATALITY/INJURY INFORMATION

NAME	NRIC/FIN	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL

### **REPORT ISSUED BY:**

ANG LI FENG

for COMMISSIONER

SINGAPORE CIVIL DEFENCE FORCE

This is a computer generated report. No signature is required.

<sup>\*</sup>This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.