

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KIM SOON LEE (LIM) HEAVY TRANSPORT
PTE LTD
200 BEDOK SOUTH AVENUE 1
SINGAPORE 469331

Contact : 92472397 83023137

TP INC
Hui Rong

TAX INVOICE

Repair Code : CLM18275

Date in : 18/06/2024

Vehicle Num. : GBF533Z

Model : MITSUBISHI CANTER FEA01BR1SDEB (CBU)

Chassis/Eng# : FEA01BA20233/4P10C17286

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR END PANEL <i>Regis</i>	1	397.00	+ 397.00
REAR END PANEL SIDE BRACKET L/R <i>re</i>	2	205.00	+ 410.00
REAR END PANEL SIDE BRACKET STOPPER L/R <i>re</i>	2	48.00	+ 96.00
REAR NUMBER PLATE LAMP <i>lit</i>	1	198.00	✓ 198.00
REAR NUMBER PLATE LAMP BRACKET <i>Best</i>	1	269.00	✓ 269.00
REAR TAILGATE <i>Dented</i>	1	2156.00	1671- 2,156.00
REAR TAILGATE HINGES <i>re</i>	3	78.00	304- 234.00
REAR TAILLAMP ASSY L/R <i>LH comLd</i>	2	396.90	1831.50- 793.80
Subtotal before discount			4,553.80
Percentage discount 25%			1,138.45
Sub-total 1			3,415.35
REAR CROSS BAR <i>Regis</i>	1	250.00	✓ 250.00
REAR CROSS BAR STICKER - SET <i>re</i>	1	250.00	60- 250.00
REAR NUMBER PLATE <i>Best</i>	1	25.00	✓ 25.00
REAR STEP BRACKET <i>Best</i>	1	300.00	180- 300.00
REAR TAILGATE '13PAX' STICKER <i>re</i>	1	25.00	15- 25.00
REAR TAILGATE '70KM' STICKER <i>re</i>	1	25.00	15- 25.00
REAR TAILGATE COMPANY STICKER - SET <i>New</i>	1	400.00	200- 400.00

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KIM SOON LEE (LIM) HEAVY TRANSPORT
PTE LTD
200 BEDOK SOUTH AVENUE 1
SINGAPORE 469331

Contact : 92472397 83023137

TAX INVOICE

Repair Code : CLM18275

Date in : 18/06/2024

Vehicle Num. : GBF533Z

Model : MITSUBISHI CANTER FEA01BR1SDEB (CBU)

Chassis/Eng# : FEA01BA20233/4P10C17286

Subtotal before discount	1,275.00
Percentage discount 0%	0.00
Sub-total 2	1,275.00
Parts-total	4,690.35

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,880.00
Parts & Labour Total	6,570.35

920 30 80.00
450 900.00
400 800.00
40 100.00

Adrian Lim
1/5 19/06/24
04 Days

*** This is a computer-generated document which requires no signature. ***

page 2

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 3246.50
1/5: 2.6K ✓